

# Final Reclamation Inspection

February 6, 2026

Operator: KERR MCGEE OIL & GAS ONSHORE LP

Location ID: 332954

Inspection Document #: 720300098

Weld County, CO

Isaac Thibedeau  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources


Inspection Photos

Location Name: HSR-KNOX-65N67W 3NWSE

Location ID: 332954

Feb 6, 2026 at 1:00:42 PM  
+40.425150,-104.880053  
110° E  
Greeley CO 80634  
United States

Feb 6, 2026 at 1:01:39 PM  
+40.425093,-104.879502  
54° NE  
Greeley CO 80634  
United States



**Photo 1.** . Photo taken from the access road. The access road has not been reclaimed and remains bare. There is evidence of raindrop-impact erosion, and a high risk of stormwater erosion on bare soil along the access road.

**Photo 2.** Photo taken on the access road going to the location. See the comment under photo 1.



Inspection Photos

Location Name: HSR-KNOX-65N67W 3NWSE

Location ID: 332954



**Photo 3.** Photo taken from the access road. See the comment in photo 1.



**Photo 4.** Photo taken from the access road showing minimal evidence of drill seeding rows and predominantly bare soil.



## Inspection Photos

Location Name: HSR-KNOX-65N67W 3NWSE

Location ID: 332954



**Photo 5.** Photo taken from the southern end of the location, facing northwest. Weeds are present on the location and in the bar areas. Reclamation was started, as evidenced by the drill seeing rows; however, it does not seem to be progressing.

**Photo 6.** Photo taken from location facing north east. See comment in photo 5.



## Inspection Photos

Location Name: HSR-KNOX-65N67W 3NWSE

Location ID: 332954



**Photo 7.** Photo taken from southwestern edge of location facing east. Well pad has undesirable annual vegetation present throughout the location.



**Photo 8.** Photo taken from the southeast side of the well pad facing west, showing undesirable annual vegetation growing on the location.



Inspection Photos  
Location Name: HSR-KNOX-65N67W 3NWSE  
Location ID: 332954

Feb 6, 2026 at 1:08:41 PM  
+40.427231,-104.877854  
354° N  
Greeley CO 80634  
United States



**Photo 9.** Photo taken from north eastern side of well pad. Redtail hawk observed at nest outlined in red circle. Nest is less than 400 feet the northeast of the well pad.

