

# Final Reclamation Inspection

February 6, 2026

Operator: KERR MCGEE OIL & GAS ONSHORE LP

Location ID: 464086

Inspection Document #: 720300113

Weld County, CO

Isaac Thibedeau  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos

Location Name: HSR-KNOX-65N67W-TANK 3NWSE

Location ID: 464086



**Photo 1.** Photo taken from the southeastern corner of the location. Most of the location is either bare exposed soil or undesirable annual weed species.

**Photo 2.** Photo taken from the location, facing north west; see comment under photo 1.

## Inspection Photos

Location Name: HSR-KNOX-65N67W-TANK  
3NWSE  
Location ID: 464086



**Photo 3.** Photo taken from location facing northeast, see comment under photo 1.



**Photo 4.** Photo taken from the location facing North. See comment under photo 1

## Inspection Photos

Location Name: HSR-KNOX-65N67W-TANK 3NWSE

Location ID: 464086



**Photo 5.** Photo taken from the western edge of the location, facing east. See comment under photo 1.



**Photo 6.** Photo taken from the location, facing south, showing undesirable annual weeds present on the site.



## Inspection Photos

Location Name: HSR-KNOX-65N67W-TANK 3NWSE

Location ID: 464086



**Photo 7.** Photo taken from the location facing west showing significant bare areas, which are a concern for stormwater erosion.



**Photo 8.** Photo taken on location facing northwest. See comment under photo 7.