

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP EAST DRAGON TRAIL #2001 PAD

Location ID: 314305

Date: 02/26/2026



Photo # 2554 Entrance to location



Photo # 2557 Location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP EAST DRAGON TRAIL #2001 PAD

Location ID: 314305

Date: 02/26/2026



Photo # 2555 Location



Photo # 2563 Location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP EAST DRAGON TRAIL #2001 PAD

Location ID: 314305

Date: 02/26/2026



Photo # 2575 SE corner of location



Photo # 2576 NE corner of location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP EAST DRAGON TRAIL #2001 PAD

Location ID: 314305

Date: 02/26/2026



Photo # 2577 NW corner of location



Photo # 2578 SW corner of location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP EAST DRAGON TRAIL #2001 PAD

Location ID: 314305

Date: 02/26/2026



Photo # 2562 Weeds/undesirable plant species on location

Photo # 2569 Weeds/undesirable plant species on location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP EAST DRAGON TRAIL #2001 PAD

Location ID: 314305

Date: 02/26/2026



Photo # 2570 Weeds/undesirable plant species on location



Photo # 2573 Weeds/undesirable plant species on location