

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DRAGON TRAIL UNIT #1031 PAD

Location ID: 314749

Date: 03/2/2026



Photo # 2588 Entrance to location



Photo # 2591 Location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DRAGON TRAIL UNIT #1031 PAD

Location ID: 314749

Date: 03/2/2026



Photo # 2590 Location



Photo # 2593 Location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DRAGON TRAIL UNIT #1031 PAD

Location ID: 314749

Date: 03/2/2026



Photo # 2599 SW corner of location



Photo # 2600 NW corner of location

Inspection/Audit Photos

Location: UTAH GAS OP LTD DBA UTAH GAS CORP DRAGON TRAIL UNIT #1031 PAD

Location ID: 314749

Date: 03/2/2026



Photo # 2601 SE corner of location



Photo # 2602 SW corner of location