CDH Consulting, LLC
Thornton, Colorado
720.431.7468
www.CDHConsult.com

Closure Investigation and Environmental Summary
WOLFE USX CC07-25 Wellhead & Flowline
ECMC Remediation Project #33031
Weld County, Colorado

Attachments:

Field Form

Boring Logs

Figure 1 – Site Location Map

Figure 2 – Soil Sample and Field Screening Locations Map

Figure 3 – Supplemental Site Investigation Map

Table 1 – Field Data Summary Table

Table 2 –Summary of Volatile Organic Soil Chemistry Data

Table 3 – Summary of Polycyclic Aromatic Hydrocarbon Soil Chemistry Data

Table 4 – Summary of Soil Suitability for Reclamation

Table 5 – Summary of Metals in Soil Chemistry Data

Photographic Log

CDH Consulting, LLC
Thornton, Colorado
720.431.7468
www.CDHConsult.com

FIELD FORM

SITE NAME / REM: Wolfe USX CC07-25 / REM # 33031	DATE: 2/4/2026	WEATHER: 30F and sunny
TYPE OF WORK: Background Sampling and Wellhead Re-sampling	CLIENT: Noble Energy Inc.	
LAT/LONG: 40.323628, -104.485157	PERSONNEL: SHG and JW	
ESTIMATED DEPTH TO GROUNDWATER: None encountered	OTHER OBSERVATIONS: None	

SOIL SAMPLING

Date	Soil Sample ID	Soil Type	PID (ppm)	Staining (Y/N)	Odor (Y/N)	Time	Sent to lab on Ice? (Y/N)
2/4/2026	FLR01@4'	SP	0.9	N	N	9:49	Y
2/4/2026	BKG04@4'	SP	0.4	N	N	10:02	Y
2/4/2026	BKG04@6.5'	SP	0.1	N	N	10:08	Y
2/4/2026	BKG05@4'	SP	0.1	N	N	9:50	Y
2/4/2026	BKG05@6.5'	SP	0.1	N	N	9:56	Y
2/4/2026	BKG06@4'	SP	0.1	N	N	10:12	Y
2/4/2026	BKG06@6.5'	SP	0.2	N	N	10:18	Y

FACILITY INFRASTRUCTURE

EQUIPMENT	Quantity
Above Ground Storage Tank (AST)	-
Buried or Partially Buried Vessel	-
Separator	-
Emission Control Device (ECD)	-
Dump Line	-
Wellhead	-
Flowline	-
Third Party Equipment:	-
Other:	

Soil Loads Removed

IMPACTED SOIL IDENTIFIED? No

ESTIMATED VOLUME OF IMPACTS:

Date	Number	CY
Total Removed		

Disposal Facility:

Groundwater Recovery

DATE GW ENCOUNTERED:	DEPTH:

GROUNDWATER IN CONTACT WITH IMPACTED SOIL?

LNAPL OR SHEEN OBSERVED ON GW?

GROUNDWATER SAMPLING

Date/Time	Groundwater Sample ID	Depth Collected	Turbid?	Sheen?	Odor?	Photo?	Sent to lab on Ice? (Y/N)

Date	BBLS
Total Removed	

Disposal Facility:

CDH CONSULTING

CDH Consulting, LLC
Thornton, Colorado
720.431.7468
www.CDHConsult.com

BORING LOGS

Location Map:



CDH CONSULTING

CDH Consulting, LLC
www.CDHConsult.com

BORING LOG/MONITORING WELL COMPLETION DIAGRAM

Boring/Well Number: FLR01@4'	Project: Wolfe USX CC07-25
Date: 2/4/26	Client: Chevron
Logged By: SHG	Drilled By: CDH
Elevation:	Detector:
Drilling Method: Hand Auger	Sampling Method: Continuous
Gravel Pack: N/A	Seal: N/A	Grout: N/A
Casing Type: N/A	Diameter: N/A Length: N/A	Hole Diameter: 3.25"	Depth to Liquid:
Screen Type: N/A Slot: N/A	Diameter: N/A Length: N/A	Total Depth:	Depth to Water:

Penetration Resistance	Moisture Content	Vapor (ppm)	Staining	Sample #	Depth (ft. bgs.)	Sample Run	Soil/Rock Type	Lithology/Remarks	Well Completion
	Dry		No	FLR1	0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15		SP	0-4' Poorly graded Sand w/ med grain size. Light brown color	

Location Map:

CDH CONSULTING

CDH Consulting, LLC
www.CDHConsult.com

BORING LOG/MONITORING WELL COMPLETION DIAGRAM

Boring/Well Number: BHG04	Project: Wolfe USX CC07-25
Date: 2/4/26	Client: Chevron
Logged By: SHG	Drilled By: CDH
Elevation:	Detector:
Drilling Method: Hand Auger	Sampling Method: Continuous
Gravel Pack: N/A	Seal: N/A	Grout: N/A
Casing Type: N/A	Diameter: N/A Length: N/A	Hole Diameter: 3.25"	Depth to Liquid:
Screen Type: N/A Slot: N/A	Diameter: N/A Length: N/A	Total Depth:	Depth to Water:

Penetration Resistance	Moisture Content	Vapor (ppm)	Staining	Sample #	Depth (ft. bgs.)	Sample Run	Soil/Rock Type	Lithology/Remarks	Well Completion
	Dry ↓ Slightly moist ↓		NO ↓ ↓	BHG04@4' BHG04@6.5'	0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15		SP ↓	0-5' Poorly graded sand w/ med grain size. Light brown color. 5-6.5 S.A., slightly larger grain size, slightly moist	

Location Map:



CDH CONSULTING

CDH Consulting, LLC
www.CDHConsult.com

BORING LOG/MONITORING WELL COMPLETION DIAGRAM

Boring/Well Number: BS605		Project: Wolfe USX CC07-25	
Date: 2/4/26		Client: Chevron	
Logged By: Jack Hilley		Drilled By: CDH	
Elevation: 4800'	Detector: Minirae 3000	Drilling Method: Hand Auger	Sampling Method: Continuous
Gravel Pack: N/A		Seal: N/A	Grout: N/A
Casing Type: N/A		Diameter: N/A Length: N/A	Hole Diameter: 3.25" / Depth to Liquid: N/A
Screen Type: N/A Slot: N/A		Diameter: N/A Length: N/A	Total Depth: 6.5' / Depth to Water: N/A

Penetration Resistance	Moisture Content	Vapor (ppm)	Staining	Sample #	Depth (ft. bgs.)	Sample Run	Soil/Rock Type	Lithology/Remarks	Well Completion
	Dry	0.1	No	BS605 @1'	0 1 2	1	SC SP	0-1' Dry. Medium brown SC. Low cohesion but frozen. Clayey sand with trace gravel. Farm soil	
	Dry				3 4		SP	1-6.5' Light brown SP poorly graded sand. Easy to dig through and loose. Dry,	
	Dry	0.1	No	BS605 @6.5'	5 6 7	2	SP	grains get smaller the deeper you go.	
					8 9 10 11 12 13 14 15				

Location Map:



CDH CONSULTING

CDH Consulting, LLC
www.CDHConsult.com

BORING LOG/MONITORING WELL COMPLETION DIAGRAM

Boring/Well Number: Blsb06	Project: Wolfe USX CC07-25
Date: 2/4/26	Client: Chevron
Logged By: Jack Willey	Drilled By: CDH
Elevation: 4800'	Detector: Minirae 3000
Drilling Method: Hand Auger	Sampling Method: Continuous
Gravel Pack: N/A	Seal: N/A
Grout: N/A	
Casing Type: N/A	Diameter: N/A Length: N/A
Hole Diameter: 3.25"	Depth to Liquid: N/A
Screen Type: N/A Slot: N/A	Diameter: N/A Length: N/A
Total Depth: 6.5'	Depth to Water: N/A

Penetration Resistance	Moisture Content	Vapor (ppm)	Staining	Sample #	Depth (ft. bgs.)	Sample Run	Soil/Rock Type	Lithology/Remarks	Well Completion
	Dry	0.1	No	Blsb06 @1'	0	1	SC	0-1' Dry. Medium brown SC. Low cohesion, not frozen. clayey sand with trace gravel, Farm soil,	
	Dry				1		SP		
					2		SP	1-6.5' Light brown SP poorly graded sand, Tight to dig through and loose. Dry. Grains get smaller the deeper you go.	
	Dry	0.2	No	Blsb06 @6.5'	3	2	SP		
					4				
					5				
					6				
					7				
					8				
					9				
					10				
					11				
					12				
					13				
					14				
					15				

CDH Consulting, LLC
Thornton, Colorado
720.431.7468
www.CDHConsult.com

FIGURES





Figure 1
Site Location Map
WOLFE USX CC07-25

NESW-SEC 7-T4N-R63W
Weld County, Colorado
Noble Energy Inc

Site Location



Figure 2
Soil Sample and Field Screening Locations Map

WOLFE USX CC07-25
NESW-SEC 7-T4N-R63W
Weld County, Colorado
Noble Energy Inc.

- Screening Point (Tasman)
- Soil Sample (Tasman)
- Soil Sample (CDH)
- Soil Sample (Entrada)
- Screening Point (Entrada)
- Background Sample Collected on 1/31/2025 by Tasman
- Background Sample Collected on 2/4/2026 by CDH
- Flowline Removed





Figure 3
Supplemental Site Investigation Map

WOLFE USX CC07-25
NESW-SEC 7-T4N-R63W
Weld County, Colorado
Noble Energy Inc.

- Screening Point (Tasman)
- Soil Sample (Tasman)
- Soil Sample (CDH)
- Soil Sample (Entrada)
- Screening Point (Entrada)
- Background Sample Collected on 1/31/2025 by Tasman
- Background Sample Collected on 2/4/2026 by CDH
- Proposed BKG
- Flowline Removed

CDH Consulting, LLC
Thornton, Colorado
720.431.7468
www.CDHConsult.com

TABLES

TABLE 1
FIELD DATA SUMMARY TABLE
NOBLE 100322
WOLFE USX CC07-25, WELD COUNTY, COLORADO
REM # 33031

Sample ID	Sample Date	Depth (ft)	GPS Data Latitude/Longitude		PDOP Value	VOC Concentration (ppm)	Consultant Who Collected Samples
WH01@6 [1]	3/27/2024	6	40.323631	-104.485132	NM	0.0	Entrada
FLR01@6 [1]	3/27/2024	4	40.323628	-104.485157	NM	0.0	Entrada
WH01-N@4	3/27/2024	4	40.323647	-104.485139	NM	0.0	Entrada
WH01-E@4	3/27/2024	4	40.323616	-104.485130	NM	0.0	Entrada
WH01-S@4	3/27/2024	4	40.323634	-104.485107	NM	0.0	Entrada
FL01-01@4'	1/30/2025	4	40.326500	-104.482971	0.900000	0.1	Tasman
FL01-02@4'	1/30/2025	4	40.326079	-104.483453	0.800000	0.2	Tasman
FL01-03@4'	1/30/2025	4	40.325361	-104.484238	0.800000	0.0	Tasman
FL01-04@4'	1/30/2025	4	40.324707	-104.484924	0.800000	0.1	Tasman
FL01-05@4'	1/30/2025	4	40.325735	-104.483833	0.900000	0.0	Tasman
FL01-06@4'	1/30/2025	4	40.324390	-104.485271	0.700000	0.0	Tasman
FL01-07@4'	1/30/2025	4	40.324998	-104.484623	0.800000	0.0	Tasman
FL01-08@4'	1/30/2025	4	40.324084	-104.485614	0.900000	0.3	Tasman
BKG01@0-6'[A]	1/31/2025	0-0.5	40.325815	-104.482950	1.100000	0.1	Tasman
BKG01@1'[A]	1/31/2025	1	40.325815	-104.482950	1.100000	0.2	Tasman
BKG01@2'[A]	1/31/2025	2	40.325815	-104.482950	1.100000	0.0	Tasman
BKG01@2.5'[A]	1/31/2025	2.5	40.325815	-104.482950	1.100000	0.0	Tasman
BKG01@3'[A]	1/31/2025	3	40.325815	-104.482950	1.100000	0.0	Tasman
BKG01@4'[A]	1/31/2025	4	40.325815	-104.482950	1.100000	0.0	Tasman
BKG02@0-6'[A]	1/31/2025	0-0.5	40.325993	-104.483831	0.900000	0.0	Tasman
BKG02@1'[A]	1/31/2025	1	40.325993	-104.483831	0.900000	0.0	Tasman
BKG02@2'[A]	1/31/2025	2	40.325993	-104.483831	0.900000	0.0	Tasman
BKG02@2.5'[A]	1/31/2025	2.5	40.325993	-104.483831	0.900000	0.0	Tasman
BKG02@3'[A]	1/31/2025	3	40.325993	-104.483831	0.900000	0.0	Tasman
BKG02@4'[A]	1/31/2025	4	40.325993	-104.483831	0.900000	0.0	Tasman
BKG03@0-6'[3]	1/31/2025	0-0.5	40.326164	-104.484558	1.100000	0.1	Tasman
BKG03@1'[3]	1/31/2025	1	40.326164	-104.484558	1.100000	0.2	Tasman
BKG03@2'[3]	1/31/2025	2	40.326164	-104.484558	1.100000	0.0	Tasman
BKG03@2.5'[3]	1/31/2025	2.5	40.326164	-104.484558	1.100000	0.0	Tasman
BKG03@3'[3]	1/31/2025	3	40.326164	-104.484558	1.100000	0.0	Tasman
BKG03@4'[3]	1/31/2025	4	40.326164	-104.484558	1.100000	0.0	Tasman
BKG04@0-6'[A]	1/31/2025	0-0.5	40.325305	-104.477916	0.800000	0.1	Tasman
BKG04@1'[A]	1/31/2025	1	40.325305	-104.477916	0.800000	0.0	Tasman
BKG04@2'[A]	1/31/2025	2	40.325305	-104.477916	0.800000	0.0	Tasman
BKG04@2.5'[A]	1/31/2025	2.5	40.325305	-104.477916	0.800000	0.0	Tasman
BKG04@3'[A]	1/31/2025	3	40.325305	-104.477916	0.800000	0.0	Tasman
BKG04@4'[A]	1/31/2025	4	40.325305	-104.477916	0.800000	0.0	Tasman
BKG05@0-6'[A]	1/31/2025	0-0.5	40.324770	-104.474511	0.800000	0.0	Tasman
BKG05@1'[A]	1/31/2025	1	40.324770	-104.474511	0.800000	0.0	Tasman
BKG05@2'[A]	1/31/2025	2	40.324770	-104.474511	0.800000	0.0	Tasman
BKG05@2.5'[A]	1/31/2025	2.5	40.324770	-104.474511	0.800000	0.1	Tasman
BKG05@3'[A]	1/31/2025	3	40.324770	-104.474511	0.800000	0.0	Tasman
BKG05@4'[A]	1/31/2025	4	40.324770	-104.474511	0.800000	0.2	Tasman
BKG06@0-6'[A]	1/31/2025	0-0.5	40.324642	-104.473556	0.800000	0.0	Tasman
BKG06@1'[A]	1/31/2025	1	40.324642	-104.473556	0.800000	0.0	Tasman
BKG06@2'[A]	1/31/2025	2	40.324642	-104.473556	0.800000	0.0	Tasman
BKG06@2.5'[A]	1/31/2025	2.5	40.324642	-104.473556	0.800000	0.0	Tasman
BKG06@3'[A]	1/31/2025	3	40.324642	-104.473556	0.800000	0.0	Tasman
BKG06@4'[A]	1/31/2025	4	40.324642	-104.473556	0.800000	0.0	Tasman
WH01@6.5	2/6/2025	6.5	40.323631	-104.485132	NM	0.0	Entrada
FLR01@4'	2/4/2026	4	40.323631	-104.485156	0.939886	0.9	CDH
BKG04@4' [3]	2/4/2026	4	40.323781	-104.485355	0.885677	0.4	CDH
BKG04@6.5' [3]	2/4/2026	6.5	40.323781	-104.485355	0.885677	0.1	CDH
BKG05@4'	2/4/2026	4	40.323814	-104.484964	0.900000	0.1	CDH
BKG05@6.5'	2/4/2026	6.5	40.323814	-104.484964	0.900000	0.1	CDH
BKG06@4'	2/4/2026	4	40.323581	-104.484811	1.000000	0.1	CDH
BKG06@6.5'	2/4/2026	6.5	40.323581	-104.484811	1.000000	0.2	CDH

1. Global Positioning System (GPS) data is provided in decimal degrees using North American Datum (NAD) 83 UTM Zone 13 North.

2. Volatile organic compound (VOC) concentrations are measured in the field using a photoionization detector (PID).

[1] Indicates sample IDs that were determined to be outside of the required temperature preservation range when delivered to the laboratory. Re-sampling was conducted on 2/6/2025 and 2/4/2026.

[3] Indicates background samples were determined to be within the oil and gas impacted area and will not be used to determine site specific background parameters.

[A] Background samples collected during decommissioning of nearby Wolfe USX CC 7-10 (REM#32569)

PDOP = Position Dilution of Precision

ppm = Parts per million

ft = Feet

TABLE 2
SUMMARY OF VOLATILE ORGANIC SOIL CHEMISTRY DATA
NOBLE 100322
WOLFE USX CC07-25, WELD COUNTY, COLORADO
REM # 33031

Sample ID	Sample Date	Depth (ft)	Benzene (mg/kg)	Toluene (mg/kg)	Ethyl-Benzene (mg/kg)	Xylenes (mg/kg)	1,2,4-Trimethyl-Benzene (mg/kg)	1,3,5-Trimethyl-Benzene (mg/kg)	Naphthalene (mg/kg)	TPH (mg/kg)	TPH GRO (mg/kg)	TPH DRO (mg/kg)	TPH ORO (mg/kg)
ECMC Table 915-1 Limits (Residential SSL)			1.2	490	5.8	58	30	27	2	500		500**	
ECMC Table 915-1 Limits (Protection of Groundwater SSL)			0.0026	0.69	0.78	9.9	0.0081	0.0087	0.0038	500		500**	
WH01@6 [1]	3/27/2024	6	*<0.00200*	*<0.00200*	*<0.00200*	*<0.00200*	*<0.00200*	*<0.00200*	*<0.002*	*<125.200*	*<0.200*	*<25.0*	*<100*
FLR01@6 [1]	3/27/2024	4	*<0.00200*	*<0.00200*	*<0.00200*	*<0.00200*	*<0.00200*	*<0.00200*	*<0.002*	*<125.200*	*<0.200*	*<25.0*	*<100*
FL01-04@4'	1/30/2025	4	*<0.0020*	*<0.0050*	*<0.0050*	*<0.010*	*<0.0050*	*<0.0050*	*<0.0038*	*<100.50*	*<0.50*	*<50*	*<50*
FL01-08@4'	1/30/2025	4	*<0.0020*	*<0.0050*	*<0.0050*	*<0.010*	*<0.0050*	*<0.0050*	*<0.0038*	*<100.50*	*<0.50*	*<50*	*<50*
WH01@6.5	2/6/2025	6.5	*<0.00200*	*<0.00200*	*<0.00200*	*<0.00200*	*<0.00200*	*<0.00200*	*<0.00343*	*<125.200*	*<0.200*	*<25.0*	*<100*
FLR01@4'	2/4/2026	4	*<0.00053*	*<0.0053*	*<0.0011*	*<0.0021*	*<0.0053*	*<0.0053*	*<0.0021*	*<10.6*	*<0.21*	*<4.2*	*<6.2*

1. Bold values exceed the ECMC Table 915-1 limit(s)
2. Red & blue highlighted soil analytical values indicate an exceedance of the referenced soil screening level (SSL)
3. * Indicates laboratory minimum detection limit in excess of SSL
4. ** Summation of GRO+DRO+ORO must be less than 500 mg/kg
5. Samples are reported as dry weight unless otherwise indicated in the laboratory PDF report(s).

[1] Indicates sample IDs that were determined to be outside of the required temperature preservation range when delivered to the laboratory. Re-sampling was conducted on 2/6/2025 and 2/4/2026.

(<) = Analytical result is less than the indicated laboratory reporting limit.
TPH-GRO = Total petroleum hydrocarbons - gasoline range organics
TPH-DRO = Total petroleum hydrocarbons - diesel range organics
TPH-ORO = Total petroleum hydrocarbons - oil range organics
mg/kg = Milligrams per kilogram
ft = Feet
bgs = Below ground surface

TABLE 3
SUMMARY OF POLYCYCLIC AROMATIC HYDROCARBON SOIL CHEMISTRY DATA
NOBLE 100322
WOLFE USX CC07-25, WELD COUNTY, COLORADO
REM # 33031

Sample ID	Sample Date	Depth (ft)	Acenaphthene (mg/kg)	Anthracene (mg/kg)	Benzo (a) Anthracene (mg/kg)	Benzo (a) Pyrene (mg/kg)	Benzo (b) Fluoranthene (mg/kg)	Benzo (k) Fluoranthene (mg/kg)	Chrysene (mg/kg)	Dibenzo (a,h) Anthracene (mg/kg)	Fluoranthene (mg/kg)	Fluorene (mg/kg)	Indeno (1,2,3-cd) Pyrene (mg/kg)	Pyrene (mg/kg)	1-Methyl - Naphthalene (mg/kg)	2-Methyl-Naphthalene (mg/kg)
ECMC Table 915-1 Limits (Residential SSL)			360	1800	1.1	0.11	1.1	11	110	0.11	240	240	1.1	180	18	24
ECMC Table 915-1 Limits (Protection of Groundwater SSL)			0.55	5.8	0.011	0.24	0.3	2.9	9	0.096	8.9	0.54	0.98	1.3	0.006	0.019
WH01@6 [1]	3/27/2024	6	*<0.020*	*<0.020*	*<0.005*	*<0.020*	*<0.020*	*<0.020*	*<0.020*	*<0.020*	*<0.020*	*<0.020*	*<0.020*	*<0.020*	*<0.002*	*<0.002*
FLR01@6 [1]	3/27/2024	4	*<0.020*	*<0.020*	*<0.005*	*<0.020*	*<0.020*	*<0.020*	*<0.020*	*<0.020*	*<0.020*	*<0.020*	*<0.020*	*<0.020*	*<0.002*	*<0.002*
FL01-04@4'	1/30/2025	4	*<0.00500*	*<0.00500*	*<0.00500*	*<0.00500*	*<0.00500*	*<0.00500*	*<0.00500*	*<0.00500*	0.0107	*<0.00500*	*<0.00500*	0.00742	*<0.00500*	*<0.00500*
FL01-08@4'	1/30/2025	4	*<0.00500*	*<0.00500*	*<0.00500*	*<0.00500*	*<0.00500*	*<0.00500*	*<0.00500*	*<0.00500*	*<0.00500*	*<0.00500*	*<0.00500*	*<0.00500*	*<0.00500*	*<0.00500*
WH01@6.5	2/6/2025	6.5	*<0.00343*	*<0.00343*	*<0.00343*	*<0.00343*	*<0.00343*	*<0.00343*	*<0.00343*	*<0.00343*	*<0.00343*	*<0.00343*	*<0.00343*	*<0.00343*	*<0.00343*	*<0.00343*
FLR01@4'	2/4/2026	4	*<0.0042*	*<0.0042*	*<0.0053*	*<0.0042*	*<0.0042*	*<0.0042*	*<0.0042*	*<0.0042*	*<0.0042*	*<0.0042*	*<0.0042*	*<0.0042*	*<0.0042*	*<0.0042*

1. Bold values exceed the ECMC Table 915-1 limit(s)
2. Red & blue highlighted soil analytical values indicate an exceedance of the referenced soil screening level (SSL)
3. * Indicates laboratory minimum detection limit in excess of SSL
4. Samples are reported as dry weight unless otherwise indicated in the laboratory PDF report(s).

[1] Indicates sample IDs that were determined to be outside of the required temperature preservation range when delivered to the laboratory. Re-sampling was conducted on 2/6/2025 and 2/4/2026.

(<) = Analytical result is less than the indicated laboratory reporting limit.
mg/kg = Milligrams per kilogram
ft = Feet
bgs = Below ground surface

TABLE 4
SUMMARY OF SOIL SUITABILITY FOR RECLAMATION
NOBLE 100322
WOLFE USX CC07-25, WELD COUNTY, COLORADO
REM # 33031

Sample ID	Sample Date	Depth (ft)	pH (Standard Units)	EC (mmhos/cm)	SAR (Standard Units)	Boron (mg/L)
ECMC Table 915-1 Soil Suitability Limits			6 - 8.3	<4	<6	2
WH01@6 [1]	3/27/2024	6	8.17	0.685	1.11	0.114
FLR01@6 [1]	3/27/2024	4	8.19	0.918	1.23	0.136
FL01-04@4'	1/30/2025	4	**8.53**	0.774	3.21	*<2.00*
FL01-08@4'	1/30/2025	4	7.88	3.10	0.601	*<2.00*
WH01@6.5	2/6/2025	6.5	**8.41**	0.346	1.66	0.248
FLR01@4'	2/4/2026	4	7.62	1.90	2.56	0.254
BKG01@0-6"[A]	1/31/2025	0-0.5	7.63	0.57	0.815	*<2.00*
BKG01@2'[A]	1/31/2025	2	8.08	1.29	1.74	*<2.00*
BKG01@2.5'[A]	1/31/2025	2.5	7.68	1.45	1.85	*<2.00*
BKG01@3'[A]	1/31/2025	3	7.73	1.29	2.32	*<2.00*
BKG01@4[A]	1/31/2025	4	8.05	1.06	2.74	*<2.00*
BKG02@0-6"[A]	1/31/2025	0-0.5	7.23	1.70	3.31	*<2.00*
BKG02@2'[A]	1/31/2025	2	7.86	2.50	3.79	*<2.00*
BKG02@2.5'[A]	1/31/2025	2.5	7.65	2.17	3.64	*<2.00*
BKG02@3'[A]	1/31/2025	3	7.64	2.33	3.22	*<2.00*
BKG02@4'[A]	1/31/2025	4	8.21	1.46	2.21	*<2.00*
BKG03@0-6" [3]	1/31/2025	0-0.5	7.68	1.54	3.47	*<2.00*
BKG03@1' [3]	1/31/2025	2	7.75	3.46	4.09	*<2.00*
BKG03@2' [3]	1/31/2025	2.5	7.82	3.56	3.8	*<2.00*
BKG03@2.5' [3]	1/31/2025	3	7.93	2.83	4.19	*<2.00*
BKG03@3' [3]	1/31/2025	4	7.79	2.50	**6.04**	*<2.00*
BKG03@4' [3]	1/31/2025	0-0.5	7.98	1.66	3.17	*<2.00*
BKG04@2'[A]	1/31/2025	2	7.86	1.28	1.98	*<2.00*
BKG04@2.5'[A]	1/31/2025	2.5	7.64	0.90	1.99	*<2.00*
BKG04@3'[A]	1/31/2025	3	7.83	1.65	2.06	*<2.00*
BKG04@4'[A]	1/31/2025	4	**8.31**	1.39	2.1	*<2.00*
BKG05@0-6"[A]	1/31/2025	0-0.5	7.86	0.59	1.93	*<2.00*
BKG05@2'[A]	1/31/2025	2	7.9	1.48	1.75	*<2.00*
BKG05@2.5'[A]	1/31/2025	2.5	8.04	1.49	1.71	*<2.00*
BKG05@3'[A]	1/31/2025	3	7.93	1.25	1.88	*<2.00*
BKG05@4'[A]	1/31/2025	4	8.01	1.20	1.88	*<2.00*
BKG06@0-6"[A]	1/31/2025	0-0.5	7.64	1.08	2.4	*<2.00*
BKG06@2'[A]	1/31/2025	2	7.28	2.78	3.07	*<2.00*
BKG06@2.5'[A]	1/31/2025	2.5	7.87	2.47	2.84	*<2.00*
BKG06@3'[A]	1/31/2025	3	7.79	1.89	1.83	*<2.00*
BKG06@4'[A]	1/31/2025	4	7.48	1.50	1.98	*<2.00*
BKG01@4'	3/11/2025	4	8.02	2.07	2.18	0.103
BKG01@6'	3/11/2025	6	**8.51**	1.11	4.43	0.102
BKG02@4'	3/11/2025	4	7.98	2.56	3.70	0.286
BKG02@6'	3/11/2025	6	8.14	2.43	4.15	0.254
BKG03@4'	3/11/2025	4	7.96	3.95	3.94	0.288
BKG03@6'	3/11/2025	6	**8.99**	0.801	**7.65**	*<0.100*
BKG04@4' [3]	2/4/2026	4	7.64	3.1	3.26	*<0.25*
BKG04@6.5' [3]	2/4/2026	6.5	7.80	2.9	4.08	*<0.25*
BKG05@4'	2/4/2026	4	7.79	1.2	2.44	*<0.25*
BKG05@6.5'	2/4/2026	6.5	7.96	0.64	2.43	*<0.25*
BKG06@4'	2/4/2026	4	7.71	1.7	4.87	*<0.25*
BKG06@6.5'	2/4/2026	6.5	7.99	2.0	5.15	*<0.25*
Maximum Background Concentration			8.99	3.95	7.65	0.288

1. **Bold** faced values exceed the ECMC Table 915-1 limit(s), but are within background concentrations.
2. Bold faced values exceed the ECMC Table 915-1 limit(s) and native background concentrations.
3. Brown highlighted soil analytical values indicate a regulatory exceedance.
4. Samples are reported as dry weight unless otherwise indicated in the laboratory PDF report(s).

[1] Indicates sample IDs that were determined to be outside of the required temperature preservation range when delivered to the laboratory. Re-sampling was conducted on 2/6/2025 and 2/4/2026.

[3] Indicates background samples were determined to be within the oil and gas impacted area and will not be used to determine site specific background parameters.

[A] Background samples collected during decommissioning of nearby Wolfe USX CC 7-10 (REM#32569)
ft = Feet
EC = Electrical Conductivity
SAR = Sodium adsorption ratio
mmhos/cm = millimhos per centimeter
mg/L = milligrams per liter
(<) = Analytical result is less than the indicated laboratory reporting limit

TABLE 5
SUMMARY OF METALS IN SOIL CHEMISTRY DATA
NOBLE 100322
WOLFE USX CC07-25, WELD COUNTY, COLORADO
REM # 33031

Sample ID	Sample Date	Depth (ft)	Arsenic (mg/kg)	Barium (mg/kg)	Cadmium (mg/kg)	Chromium (VI) (mg/kg)	Copper (mg/kg)	Lead (mg/kg)	Nickel (mg/kg)	Selenium (mg/kg)	Silver (mg/kg)	Zinc (mg/kg)
ECMC Table 915-1 Limits (Residential SSL)			0.68	15000	71	0.3	3100	400	1500	390	390	23000
ECMC Table 915-1 Limits (Protection of Groundwater SSL)			0.29	82	0.38	0.00067	46	14	26	0.26	0.8	370
WH01@6 [1]	3/27/2024	6	**2.23**	81.2	*<0.0867*	*<0.244**	*<8.67*	5.88	5.13	*<0.225*	*<0.0867*	*<32.1*
FLR01@6 [1]	3/27/2024	4	**2.52**	49.7	*<0.0912*	*<0.244**	*<9.12*	4.29	4.02	*<0.237*	*<0.0912*	*<33.8*
FL01-04@4'	1/30/2025	4	**0.603**	**83.8**	*<0.200*	*<0.30 **	1.90	5.92	1.80	*<0.260*	0.0328	7.25
FL01-08@4'	1/30/2025	4	**0.682**	**104**	0.221	*<0.30 **	2.75	10.6	2.20	*<0.260*	0.0472	9.22
WH01@6.5	2/6/2025	6.5	**3.09**	**83.7**	*<0.0961*	*<0.317**	*<9.61*	4.13	4.62	*<0.250*	*<0.0961*	*<35.5*
FLR01@4'	2/4/2026	4	**1.7**	58.4	*<0.11*	**0.50**	4.4	4.4	4.4	*<0.21*	*<0.11*	16.1
BKG01@0-6"[A]	1/31/2025	0-0.5	**0.625**	80.9	*<0.200*	*<0.30 **	2.76	7.61	1.59	**0.299**	0.0396	11.4
BKG01@2'[A]	1/31/2025	2	**0.448**	44.5	*<0.200*	*<0.30 **	1.04	3.35	1.01	*<0.260*	*<0.0200*	3.99
BKG01@2.5'[A]	1/31/2025	2.5	**0.439**	50.5	*<0.200*	*<0.30 **	1.13	3.87	1.03	*<0.260*	*<0.0200*	4.27
BKG01@3'[A]	1/31/2025	3	**0.522**	58.2	*<0.200*	*<0.30 **	1.85	5.00	1.29	*<0.260*	0.025	7.43
BKG01@4[A]	1/31/2025	4	**0.522**	65.0	*<0.200*	*<0.30 **	1.27	4.31	1.21	*<0.260*	0.025	4.74
BKG02@0-6"[A]	1/31/2025	0-0.5	**0.644**	**119**	0.263	*<0.30 **	3.38	10.4	1.83	**0.383**	0.0482	12.6
BKG02@2'[A]	1/31/2025	2	**0.854**	**175**	0.253	*<0.30 **	2.52	12.2	2.24	*<0.260*	0.092	8.91
BKG02@2.5'[A]	1/31/2025	2.5	**0.863**	**177**	0.246	*<0.30 **	2.50	11.9	2.21	*<0.260*	0.0836	8.83
BKG02@3'[A]	1/31/2025	3	**0.855**	**167**	0.205	*<0.30 **	2.40	10.7	2.12	*<0.260*	0.0796	8.57
BKG02@4'[A]	1/31/2025	4	**0.467**	61.3	*<0.200*	*<0.30 **	1.21	3.7	1.06	*<0.260*	*<0.0200*	4.82
BKG03@0-6"[3]	1/31/2025	0-0.5	**0.671**	**146**	0.321	*<0.30 **	3.36	12.6	1.98	**0.395**	0.0621	12.8
BKG03@1'[3]	1/31/2025	2	**0.738**	**160**	0.274	*<0.30 **	2.57	11.5	2.11	*<0.260*	0.0695	8.8
BKG03@2'[3]	1/31/2025	2.5	**0.755**	**140**	0.242	*<0.30 **	2.55	9.96	2.08	*<0.260*	0.0576	9.16
BKG03@2.5'[3]	1/31/2025	3	**0.716**	**123**	0.236	*<0.30 **	2.78	11.0	2.27	*<0.260*	0.0587	9.41
BKG03@3'[3]	1/31/2025	4	**0.706**	**89.8**	0.276	*<0.30 **	2.80	11.4	2.2	*<0.260*	0.0843	9.69
BKG03@4'[3]	1/31/2025	0-0.5	**0.620**	70.0	*<0.200*	*<0.30 **	1.64	5.43	1.66	*<0.260*	0.0324	7.02
BKG04@2'[A]	1/31/2025	2	**0.632**	71.3	*<0.200*	*<0.30 **	2.61	6.31	1.68	*<0.260*	0.031	10.6
BKG04@2.5'[A]	1/31/2025	2.5	**0.613**	72.8	*<0.200*	*<0.30 **	1.95	6.04	1.54	*<0.260*	0.0311	7.91
BKG04@3'[A]	1/31/2025	3	**0.531**	58.9	*<0.200*	*<0.30 **	1.40	4.63	1.51	*<0.260*	0.0248	6.06
BKG04@4'[A]	1/31/2025	4	**0.709**	**201**	0.204	*<0.30 **	1.54	7.25	2.14	*<0.260*	0.0352	7.87
BKG05@0-6"[A]	1/31/2025	0-0.5	**0.553**	62.3	*<0.200*	*<0.30 **	3.69	6.05	1.45	**0.327**	0.0235	13.4
BKG05@2'[A]	1/31/2025	2	**0.523**	60.4	*<0.200*	*<0.30 **	1.52	4.39	1.35	*<0.260*	*<0.0200*	6.12
BKG05@2.5'[A]	1/31/2025	2.5	**0.498**	57.5	*<0.200*	*<0.30 **	1.68	4.69	1.37	*<0.260*	0.0203	6.28
BKG05@3'[A]	1/31/2025	3	**0.480**	52.0	*<0.200*	*<0.30 **	1.35	3.95	1.25	*<0.260*	*<0.0200*	5.4
BKG05@4'[A]	1/31/2025	4	**0.468**	47.5	*<0.200*	*<0.30 **	1.20	3.31	1.17	*<0.260*	*<0.0200*	4.92
BKG06@0-6"[A]	1/31/2025	0-0.5	**0.548**	76.7	*<0.200*	*<0.30 **	3.46	7.09	1.5	**0.298**	0.0269	12.8
BKG06@2'[A]	1/31/2025	2	**0.807**	**83.9**	0.221	*<0.30 **	2.69	7.36	1.52	*<0.260*	0.0294	10.1
BKG06@2.5'[A]	1/31/2025	2.5	**0.591**	78.4	*<0.200*	*<0.30 **	1.70	7.02	1.54	*<0.260*	0.0233	6.53
BKG06@3'[A]	1/31/2025	3	**0.439**	48.3	*<0.200*	*<0.30 **	1.26	3.61	1.14	*<0.260*	*<0.0200*	4.85
BKG06@4'[A]	1/31/2025	4	**0.389**	44.0	*<0.200*	*<0.30 **	1.22	3.36	1.1	*<0.260*	*<0.0200*	4.8
BKG01@4'	3/11/2025	4	**1.48**	34.3	*<0.0894*	*<0.322 **	*<8.94*	3.00	3.21	*<0.232*	*<0.0894*	*<33.1*
BKG01@6'	3/11/2025	6	**1.84**	46.6	*<0.0889*	*<0.312 **	*<8.89*	3.77	3.7	*<0.231*	*<0.0889*	*<32.9*
BKG02@4'	3/11/2025	4	**1.60**	62.4	*<0.0867*	*<0.309 **	*<8.67*	4.49	5.07	*<0.226*	*<0.0867*	*<32.1*
BKG02@6'	3/11/2025	6	**0.929**	**97.8**	0.153	*<0.294 **	*<9.18*	4.30	4.52	*<0.239*	*<0.0918*	*<34.0*
BKG03@4'	3/11/2025	4	**2.08**	74.3	0.099	*<0.216 **	*<8.46*	5.76	5.94	*<0.220*	*<0.0846*	*<31.3*
BKG03@6'	3/11/2025	6	**1.66**	40.7	*<0.0967*	*<0.421 **	*<9.67*	2.59	2.58	*<0.251*	*<0.0967*	*<35.8*
BKG04@4' [3]	2/4/2026	4	**1.7**	35.8	*<0.097*	*<0.40 **	3.1	3.4	3.4	*<0.19*	*<0.097*	11.8
BKG04@6.5' [3]	2/4/2026	6.5	**3.0**	81.6	*<0.11*	*<0.45 **	3.7	4.2	4.4	*<0.22*	*<0.11*	15.1
BKG05@4'	2/4/2026	4	**1.2**	23.1	*<0.10*	*<0.43 **	*<2.0*	2.5	2.1	*<0.20*	*<0.10*	*<10*
BKG05@6.5'	2/4/2026	6.5	**1.3**	27.4	*<0.087*	*<0.41 **	2.0	2.3	2.1	*<0.17*	*<0.087*	*<8.7*
BKG06@4'	2/4/2026	4	**1.4**	24.3	*<0.092*	*<0.40 **	2.0	2.6	2.0	*<0.18*	*<0.092*	*<9.2*
BKG06@6.5'	2/4/2026	6.5	**2.1**	33.9	*<0.092*	*<0.40 **	1.9	2.4	2.3	*<0.18*	*<0.092*	*<9.2*
1.25x Maximum Background Concentration			2.6	251	0.329	*NA*	4.6	15.3	7.4	0.479	0.1150	16.8

1. **Bold** faced values exceed the ECMC Table 915-1 limit(s), but are within 1.25x background concentrations.
2. **Bold** faced values exceed the ECMC Table 915-1 limit(s) and native background concentrations.
3. Red & blue highlighted soil analytical values indicate an exceedance of the referenced soil screening level (SSL).
4. Non-detect background results accounted for in the highest background concentration by using the reporting limit.
5. Samples are reported as dry weight unless otherwise indicated in the laboratory PDF report(s).

[1] Indicates sample IDs that were determined to be outside of the required temperature preservation range when delivered to the laboratory. Re-sampling was conducted on 2/6/2025 and 2/4/2026.

[3] Indicates background samples were determined to be within the oil and gas impacted area and will not be used to determine site specific background parameters.

[A] Background samples collected during decommissioning of nearby Wolfe USX CC 7-10 (REM#32569)

(<) = Analytical result is less than the indicated laboratory reporting limit.

mg/kg = Milligrams per kilogram

ft = Feet

* Indicates laboratory minimum detection limit in excess of SSL

NA = Not analyzed

CDH Consulting, LLC
Thornton, Colorado
720.431.7468
www.CDHConsult.com

PHOTOGRAPHIC LOG

Photographic Log
WOLFE USX CC 7-25 (REM # 33031)
Noble Energy, Inc.
2/4/2026

Photo 1: View of BKG04 sample location, facing north

Photographic Log
WOLFE USX CC 7-25 (REM # 33031)
Noble Energy, Inc.
2/4/2026

Photo 2: View of BKG05 sample location, facing southwest

Photographic Log
WOLFE USX CC 7-25 (REM # 33031)
Noble Energy, Inc.
2/4/2026

Photo 3: View of BKG06 sample location, facing west

Photographic Log
WOLFE USX CC 7-25 (REM # 33031)
Noble Energy, Inc.
2/4/2026



Photo 4: View of FLR01@4' sample location, facing east-northeast