

Environmental Inspection Photos
Location Name: Facility S4WB Sales Line
Spill ID: 493326



Operator personnel observed on location, in the process of excavating soil.



Operator equipment on location.

Environmental Inspection Photos
Location Name: Facility S4WB Sales Line
Spill ID: 493326



Soil excavated, stockpiled with no liner or stormwater BMPs.



Operator personnel within excavation at spill location.

Environmental Inspection Photos
Location Name: Facility S4WB Sales Line
Spill ID: 493326



Free product visible at bend in flowline at the base of the excavation.



Liner with partial berm adjacent to spill location. Liner has been driven over by equipment.