

Inspection Photos

03/05/2026

Operator: TEP Rocky Mountain LLC #96850

Location ID: 414294

Inspection Doc: 719200904

Garfield County, CO

Emily Gaasche
NW Reclamation Specialist
ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 414294



Photo 1: Photos showing an overview of the location looking north and south, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 414294



Photo 2: Photos showing an overview of the location looking east and west, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 414294



Photo 3: Photo showing an example of rips and tears in tanks' secondary containment black geotextile liner; comply with Rule 603.o.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 414294



Photo 4: Photo showing tire chains present near the tanks' secondary containment system. Removal is required; comply with Rule 606.a.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 414294



Photo 5: Photos showing a culvert on the northwestern portion of the site is laden with sediment and partially crushed by a rock; the black drainage pipe appears to be disconnected on the outlet side. Maintenance is required; comply with Rule 1002.f.



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 414294



Photo 6: Photos showing an example of vehicle tracking that is occurring on the working pad surface; maintenance is required. Comply with Rule 1002.f.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 414294



Photo 7: Photos showing an example of the southern interim area and a thistle skeleton; perennial grasses and shrubs are present, interim areas are progressing towards 1003 requirements. Ongoing weed management is necessary.



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources