

INSPECTION PHOTOS

Well: HILL RANCH 29-15V

API #: 05-071-07554

INSPECTION DOC #: 716302025

Operator: OGRIS OPERATING LLC 10758

Inspection date: 3/9/2026

County: Las Animas

 719-497-0446
or 911
HILL RANCH 29-15
05-071-06458
SW / SE 29-34S-67W-6
LAT. 37.050550 / LONG. -104.907950

 719-497-0446
or 911
HILL RANCH 29-15V
05-071-07554
SW / SE 29-34S-67W-6
LAT. 37 050620 / LONG. -104.908170

API# 05-071-07554

Network: Mar 9, 2026 at 1:21:04 PM MDT
Local: Mar 9, 2026 at 1:21:04 PM MDT
+37.050578, -104.908040

PHOTO 2: WELL SIGN



Network: Mar 9, 2026 at 1:20:15 PM MDT
Local: Mar 9, 2026 at 1:20:15 PM MDT
+37.050619,-104.908515

PHOTO 3: LOCATION.



Network: Mar 9, 2026 at 1:20:49 PM MDT
Local: Mar 9, 2026 at 1:20:49 PM MDT
+37.050604, -104.908256

PHOTO 4: 29-15V WELLHEAD AND EQUIPMENT.



PHOTO 5: 29-15 WELLHEAD AND EQUIPMENT.