

KPK
Central tank battery
Location ID: 450391



Recent inspection/audit of crude tanks and fiberglass patch



Previous inspection/audit of crude tanks and fiberglass patch

KPK
Central tank battery
Location ID: 450391



Recent inspection/audit of staining under load out bucket

Previous inspection/audit of staining under load out bucket

KPK
Central tank battery
Location ID: 450391



Recent inspection/audit of bucket with crude and staining



Previous inspection/audit of bucket with crude and staining

KPK
Central tank battery
Location ID: 450391



Recent inspection/audit of thief hatch being held shut with a C-clamp, lack of mechanical integrity.



Previous inspection /audit of thief hatch being held shut with a C-clamp, lack of mechanical integrity.

KPK
Central tank battery
Location ID: 450391



Recent inspection /audit of location



Previous inspection /audit of location

KPK
Central tank battery
Location ID: 450391



Recent inspection /audit of staining

Previous inspection /audit of staining

KPK
Central tank battery
Location ID: 450391



Recent inspection /audit of illegible tank labeling



Previous inspection /audit of illegible tank labeling

KPK
Central tank battery
Location ID: 450391



Recent inspection /audit of illegible tank labeling



Previous inspection /audit of illegible tank labeling

KPK
Central tank battery
Location ID: 450391



Recent inspection /audit of illegible tank labeling and debris



Previous inspection /audit of illegible tank labeling and debris

KPK
Central tank battery
Location ID: 450391



Recent inspection /audit of illegible tank labeling



Previous inspection /audit of illegible tank labeling

KPK
Central tank battery
Location ID: 450391



Recent inspection /audit photo of ECD running



Previous inspection /audit photo of ECD running

KPK
Central tank battery
Location ID: 450391



Weeds throughout secondary containment and debris



Weeds throughout secondary containment

KPK
Central tank battery
Location ID: 450391



ECD



Weeds throughout secondary containment

KPK
Central tank battery
Location ID: 450391



Multiple stains



Load line not capped

KPK
Central tank battery
Location ID: 450391



Multiple stains



Multiple stains

KPK
Central tank battery
Location ID: 450391



Multiple stains



Location

KPK
Central tank battery
Location ID: 450391



Lines from tanks that go to ECD and not metered



Open line for wildlife to enter

KPK
Central tank battery
Location ID: 450391



Lines from tanks that go to ECD

Lines from tanks that go to ECD