

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BOSELY SG 43-27 Pad

Location ID: 334621



Photo # 4524 From entrance to location




Photo # 4525 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BOSELY SG 43-27 Pad

Location ID: 334621



Photo # 4526 Location



Photo # 4527 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BOSELY SG 43-27 Pad

Location ID: 334621




Photo # 4528 Location

Photo # 4529 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BOSELY SG 43-27 Pad

Location ID: 334621



Photo # 4530 Condensate tank with open ended pipe/tank open to atmosphere (Additionally open pipe constitutes a wildlife hazard)

Photo # 4531 Condensate tank with open ended pipe/tank open to atmosphere (Additionally open pipe constitutes a wildlife hazard)

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BOSELY SG 43-27 Pad

Location ID: 334621



Photo # 4532 Condensate tank with open ended pipe/tank open to atmosphere (Additionally open pipe constitutes a wildlife hazard)



Photo # 4533 Open ended load line

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BOSELY SG 43-27 Pad

Location ID: 334621



Photo # 4534 Open ended load line



Photo # 4535 Open ended load line

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BOSELY SG 43-27 Pad

Location ID: 334621



Photo # 4536 Open ended load line



Photo # 4537 Open ended load line

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BOSELY SG 43-27 Pad

Location ID: 334621



Photo # 4538 Open ended load line



Photo # 4539 Open ended load line

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BOSELY SG 43-27 Pad

Location ID: 334621



Photo # 4540 Open ended load line



Photo # 4541 Open ended load line

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BOSELY SG 43-27 Pad

Location ID: 334621



Photo # 4542 Open ended port on production tank/tank open to atmosphere (Additionally open port constitutes a wildlife hazard)



Photo # 4543 Open ended port on production tank/tank open to atmosphere (Additionally open port constitutes a wildlife hazard)

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BOSELY SG 43-27 Pad

Location ID: 334621



Photo # 4544 Wellhead signs damaged & illegible



Photo # 4545 Wellhead signs damaged & illegible

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BOSELY SG 43-27 Pad

Location ID: 334621



Photo # 4546 Debris