

Inspection Photos
Location Name: RUEBEL ET AL 1-4
Location ID: 320254



Photo #1 Tanks, vault and weeds throughout location (in and out of berms).



Photo #2 Meter & separator and weeds throughout location (in and out of berms).

Inspection Photos
Location Name: RUEBEL ET AL 1-4
Location ID: 320254



Photo #3 Well head and weeds throughout location (in and out of berms).