

Inspection Photos

API: 071-07321

Operator: WAPITI OPERATING LLC

Inspection Date: 3/9/2026

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing east toward the location.



Inspection Photos



Photo 2. There was a dripping leak at the wellhead.



Inspection Photos



Photo 3. The well sign has fallen over and needs to be reinstalled.

