

Audit Photos

Location Name: QB ENERGY OPERATING LLC, ORCHARD UNIT-68S96W/19SWSE

Location ID: 312723

Date: 3/5/2026



Location Overview – Photo #02978



Location – Photo #02977

Audit Photos

Location Name: QB ENERGY OPERATING LLC, ORCHARD UNIT-68S96W/19SWSE

Location ID: 312723

Date: 3/5/2026



Location – Photo #02982




Unsecured Separator Door – Photo #02981

Audit Photos

Location Name: QB ENERGY OPERATING LLC, ORCHARD UNIT-68S96W/19SWSE

Location ID: 312723

Date: 3/5/2026



Tank Corrosion/Staining – Photo #02984



Tank Corrosion/Staining – Photo #02986