

# Inspection Photos

API: 017-06887

Operator: CITATION OIL & GAS CORP

Inspection Date: 3/3/2026

County: CHEYENNE



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing west at the beginning of the reclaimed access road.



## Inspection Photos



**Photo 2.** Facing north along the reclaimed access road.



## Inspection Photos



**Photo 3.** Facing north toward the location.



## Inspection Photos



**Photo 4.** Center of the location facing east. There are some areas with undesirable weeds.



## Inspection Photos



**Photo 5.** Center of the location facing north.



## Inspection Photos



**Photo 6.** Center of the location facing west.



## Inspection Photos



**Photo 7.** Center of the location facing south. There are some areas with undesirable weeds.

