

Inspection Photos
Location Name: Cundall 6-12
Location ID: 320504



Photo 1 Location access.

Photo 2 Wellsite.

Inspection Photos
Location Name: Cundall 6-12
Location ID: 320504




Photo 3 Stained soil around the wellhead.

Photo 4 Wellsite sign.

Inspection Photos
Location Name: Cundall 6-12
Location ID: 320504



Photo 5 Stained soil around the wellhead.

Photo 6 Auxiliary tank.

Inspection Photos
Location Name: Cundall 6-12
Location ID: 320504



Photo 7 Tank battery.



Photo 8 Tank battery sign.

Inspection Photos
Location Name: Cundall 6-12
Location ID: 320504




Photo 9 Tank battery.

Photo 10 Tank battery.

Inspection Photos
Location Name: Cundall 6-12
Location ID: 320504



Photo 11 Production equipment.



Photo 12 Separators.

Inspection Photos
Location Name: Cundall 6-12
Location ID: 320504



Photo 13 Gas meter Run.



Photo 14 ECDs.

Inspection Photos
Location Name: Cundall 6-12
Location ID: 320504



Photo 15 Production equipment.