

# Final Reclamation Inspection

February 12, 2026

Operator: HIGHPOINT OPERATING CORPORATION – 10071

Location ID: 476919

Inspection Document #: 718801369

Weld County, CO

Katelyn Mitchem  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: NHF-Laura/4-63-3 SWNW  
Location ID: 476919



**Photo 1.** Photo taken of the tank battery location, facing north. Photo illustrates that final reclamation does not meet Rule 1004 standards at the location as gravel, bare ground, and weedy annual vegetation were observed across the northern portion of the location.



**Photo 2.** Photo taken of the tank battery location, facing southeast. See comments under Photo 1.



Inspection Photos  
Location Name: NHF-Laura/4-63-3 SWNW  
Location ID: 476919



**Photo 3.** Photo taken of the tank battery location, facing east. See comments under Photo 1.



**Photo 4.** Photo taken of the tank battery location, facing northwest. See comments under Photo 1.



## Inspection Photos

Location Name: NHF-Laura/4-63-3 SWNW

Location ID: 476919



**Photo 5.** Photo taken of ground cover at the tank battery location. Photo illustrates gravel and weedy annual vegetation including kochia (*Bassia scoparia*).



**Photo 6.** Photo taken of the reference area to the location, west of the location, facing west. Photo illustrates perennial grass vegetation.

