

# Final Reclamation Inspection

February 12, 2026

Operator: HIGHPOINT OPERATING CORPORATION – 10071

Location ID: 306086

Inspection Document #: 718801371

Weld County, CO

Katelyn Mitchem  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: 70 RANCH #CNW 3  
Location ID: 306086



**Photo 1.** Photo taken of the well location, facing north. Photo illustrates that final reclamation activities appear to have taken place at the location, but vegetation establishment does not meet Rule 1004 standards.



**Photo 2.** Photo taken of the well location, facing east. See comments under Photo 1.

Inspection Photos  
Location Name: 70 RANCH #CNW 3  
Location ID: 306086



**Photo 3.** Photo taken of the well location, facing south. See comments under Photo 1.



**Photo 4.** Photo taken of the well location, facing west. See comments under Photo 1.



Inspection Photos  
Location Name: 70 RANCH #CNW 3  
Location ID: 306086



**Photo 5.** Photo taken of ground cover at the well location. Photo illustrates perennial grass and bare ground.



**Photo 6.** Photo taken of the access road to the location, facing northwest. Photo illustrates that final reclamation activities appear to have taken place across the access road to the location, but vegetation has not established to Rule 1004 standards.

Inspection Photos  
Location Name: 70 RANCH #CNW 3  
Location ID: 306086



**Photo 7.** Photo taken of the reference area to the location, east of the location, facing east. Photo illustrates perennial grass.

