

# Final Reclamation Inspection

February 12, 2026

Operator: HIGHPOINT OPERATING CORPORATION – 10071

Location ID: 306087

Inspection Document #: 718801373

Weld County, CO

Katelyn Mitchem  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: 70 RANCH #22-3  
Location ID: 306087



**Photo 1.** Photo taken of the well location, facing north. Photo illustrates that final reclamation activities appear to have taken place at the location, and vegetation establishment at the well location meets Rule 1004 standards.



**Photo 2.** Photo taken of the well location, facing east. See comments under Photo 1.

Inspection Photos  
Location Name: 70 RANCH #22-3  
Location ID: 306087



**Photo 3.** Photo taken of the well location, facing south. See comments under Photo 1.



**Photo 4.** Photo taken of the well location, facing west. See comments under Photo 1.

Inspection Photos  
Location Name: 70 RANCH #22-3  
Location ID: 306087



**Photo 5.** Photo taken of the access road to the location, facing west. Photo illustrates that final reclamation does not meet Rule 1004 standards along the access road as gravel and bare ground were observed across this portion of the location.



**Photo 6.** Photo taken of the access road to the location, facing east. See comments under Photo 5.

Inspection Photos  
Location Name: 70 RANCH #22-3  
Location ID: 306087



**Photo 7.** Photo taken of ground cover at the access road to the location. Photo illustrates gravel, weedy annual vegetation including kochia (*Bassia scoparia*), perennial grass, and bare ground.



**Photo 8.** Photo taken of the reference area to the location, north of the location, facing east. Photo illustrates perennial grass vegetation.

