

Final Reclamation Inspection

February 12, 2026

Operator: BONANZA CREEK ENERGY OPERATING COMPANY
LLC - 8960

Location ID: 421634

Inspection Document #: 718801381

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Park #S-4
Location ID: 421634



Photo 1. Photo taken of the multi-well location, facing north. Photo illustrates that final reclamation activities do not appear to have taken place and vegetation establishment does not meet Rule 1004 standards as bare ground and weedy annual vegetation were observed across the location. There is a fence in place around the multi-well location.



Photo 2. Photo taken of the multi-well location, facing east. See comments under Photo 1.

Inspection Photos
Location Name: Park #S-4
Location ID: 421634



Photo 3. Photo taken of the multi-well location, facing south.
See comments under Photo 1.



Photo 4. Photo taken of the multi-well location, facing west.
See comments under Photo 1.



Inspection Photos
Location Name: Park #S-4
Location ID: 421634



Photo 5. Photo taken of the well location, facing northwest. Photo illustrates that fencing is in place around the location.



Photo 6. Photo taken of the tank battery location, facing north. Photo illustrates that final reclamation activities do not appear to have taken place at the location as gravel, bare ground, and weedy annual vegetation were observed across the location.



Inspection Photos
Location Name: Park #S-4
Location ID: 421634



Photo 7. Photo taken of the tank battery location, facing southeast. See comments under Photo 5.



Photo 8. Photo taken of the tank battery location, facing south. See comments under Photo 5.

Inspection Photos
Location Name: Park #S-4
Location ID: 421634



Photo 9. Photo taken of the tank battery location, facing west. See comments under Photo 5.



Photo 10. Photo taken of the tank battery location, facing west. Photo illustrates a pile of gravel remains on the location. Weedy annual vegetation including kochia (*Bassia scoparia*) and russian thistle (*Salsola tragus*) were observed across the location.



Inspection Photos
Location Name: Park #S-4
Location ID: 421634



Photo 11. Photo taken of the access road to the location, facing northwest. Photo illustrates that vegetation establishment does not meet Rule 1004 standards along the access road. Weedy annual vegetation was observed along the road including kochia (*Bassia scoparia*) and russian thistle (*Salsola tragus*).



Photo 12. Photo taken of the reference area to the location, west of the location, facing south. Photo illustrates perennial grass vegetation.

