

Final Reclamation Inspection

February 12, 2026

Operator: BONANZA CREEK ENERGY OPERATING COMPANY
LLC - 8960

Location ID: 305241

Inspection Document #: 718801383

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: PARK #44-4
Location ID: 305241



Photo 1. Photo taken of the well location, facing north. Photo illustrates that final reclamation activities appear to have taken place, but vegetation establishment does not meet Rule 1004 standards as weedy annual vegetation including cheatgrass (*Bromus tectorum*), a List C Noxious Weed species, was observed at the location.



Photo 2. Photo taken of the well location, facing east. See comments under Photo 1.



Inspection Photos
Location Name: PARK #44-4
Location ID: 305241



Photo 3. Photo taken of the well location, facing south. See comments under Photo 1.



Photo 4. Photo taken of the well location, facing west. See comments under Photo 1.



Inspection Photos
Location Name: PARK #44-4
Location ID: 305241



Photo 5. Photo taken of the access road between the well and tank battery location, facing northwest. Photo illustrates that final reclamation activities appear to have taken place, but vegetation establishment does not meet Rule 1004 standards and gravel remains. Weedy annual vegetation including cheatgrass (*Bromus tectorum*) was observed at the location.



Photo 6. Photo taken of ground cover along the access road. Photo illustrates gravel, perennial grass, and weedy annual vegetation including cheatgrass (*Bromus tectorum*).



Inspection Photos
Location Name: PARK #44-4
Location ID: 305241



Photo 7. Photo taken of the tank battery location, facing northwest. Photo illustrates that final reclamation activities appear to have taken place, but vegetation has not established to Rule 1004 standards as weedy annual vegetation including cheatgrass (*Bromus tectorum*), a List C Noxious Weed species, was observed at the location.



Photo 8. Photo taken of the tank battery location, facing south. See comments under Photo 7.



Inspection Photos
Location Name: PARK #44-4
Location ID: 305241



Photo 9. Photo taken of the tank battery location, facing east. See comments under Photo 7.



Photo 10. Photo taken of the reference area to the location, northeast of the location, facing east. Photo illustrates perennial grass and weedy annual vegetation.

