

Final Reclamation Inspection

February 12, 2026

Operator: BONANZA CREEK ENERGY OPERATING COMPANY
LLC - 8960

Location ID: 416783

Inspection Document #: 718801387

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Croissant #24-3
Location ID: 416783



Photo 1. Photo taken of the well location, facing north. Photo illustrates that final reclamation at the location appears to meet Rule 1004 standards.



Photo 2. Photo taken of the well location, facing east. See comments under Photo 1.



Inspection Photos
Location Name: Croissant #24-3
Location ID: 416783



Photo 3. Photo taken of the well location, facing south. See comments under Photo 1.



Photo 4. Photo taken of the well location, facing west. See comments under Photo 1.

Inspection Photos
Location Name: Croissant #24-3
Location ID: 416783



Photo 5. Photo taken of the reference area to the location, west of the location, facing north. Photo illustrates perennial grass vegetation.

