

Final Reclamation Inspection

February 12, 2026

Operator: BONANZA CREEK ENERGY OPERATING COMPANY
LLC - 8960

Location ID: 331364

Inspection Document #: 718801389

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: PARK #34-4
Location ID: 331364



Photo 1. Photo taken of the well location, facing north. Photo illustrates that final reclamation activities appear to have taken place at the well location, but vegetation establishment does not meet Rule 1004 standards. Weedy annual vegetation including cheatgrass (*Bromus tectorum*), a List C Noxious Weed species, was observed across the location.



Photo 2. Photo taken of the well location, facing east. See comments under Photo 1.



Inspection Photos
Location Name: PARK #34-4
Location ID: 331364



Photo 3. Photo taken of the well location, facing south. See comments under Photo 1.



Photo 4. Photo taken of the well location, facing west. See comments under Photo 1.



Inspection Photos
Location Name: PARK #34-4
Location ID: 331364



Photo 5. Photo taken of ground cover at the well location. Photo illustrates perennial grass and cheatgrass (*Bromus tectorum*), a List C Noxious Weed species.



Photo 6. Photo taken of the reference area to the location, northwest of the location, facing west. Photo illustrates perennial grass vegetation.

