

Final Reclamation Inspection

February 13, 2026

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 317550

Inspection Document #: 718801391

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: UPRR 21 PAN AM B #1

Location ID: 317550



Photo 1. Photo taken of the well location, facing north. Photo illustrates that final reclamation activities appear to have taken place at the well location, but vegetation establishment does not meet Rule 1004 standards.



Photo 2. Photo taken of the well location, facing east. See comments under Photo 1.



Inspection Photos
Location Name: UPRR 21 PAN AM B #1
Location ID: 317550



Photo 3. Photo taken of the well location, facing south. See comments under Photo 1.



Photo 4. Photo taken of the well location, facing west. See comments under Photo 1.

Inspection Photos

Location Name: UPRR 21 PAN AM B #1

Location ID: 317550



Photo 5. Photo taken of ground cover at the well location. Photo illustrates bare ground and weedy annual vegetation including kochia (*Bassia scoparia*).



Photo 6. Photo taken of the access road to the location, facing south. Photo illustrates that vegetation has not established to Rule 1004 standards.



Inspection Photos

Location Name: UPRR 21 PAN AM B #1

Location ID: 317550



Photo 7. Photo taken of the tank battery location, facing south. Photo illustrates that final reclamation activities appear to have taken place, with evidence of drill row seeding, but vegetation has not established to Rule 1004 standards.



Photo 8. Photo taken of the tank battery location, facing west. See comments under Photo 7.



Inspection Photos

Location Name: UPRR 21 PAN AM B #1

Location ID: 317550



Photo 9. Photo taken of the tank battery location, facing north. See comments under Photo 7.



Photo 10. Photo taken of the reference area to the location, east of the location, facing east. Photo illustrates perennial grass and weedy annual vegetation. The area directly surrounding the well location is degraded prairie dog habitat. This reference area is located directly east in the adjacent field to that which contains the well and tank battery location.

