

Final Reclamation Inspection

February 13, 2026

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 327749

Inspection Document #: 718801393

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: UPRC #9-14K
Location ID: 327749



Photo 1. Photo taken of the well location, facing north. Photo illustrates that final reclamation activities appear to have taken place, with evidence of drill row seeding, but vegetation establishment does not meet Rule 1004 standards. Weedy annual vegetation including kochia (*Bassia scoparia*) was observed across the location.



Photo 2. Photo taken of the well location, facing east. See comments under Photo 1.

Inspection Photos
Location Name: UPRC #9-14K
Location ID: 327749



Photo 3. Photo taken of the well location, facing south. See comments under Photo 1.



Photo 4. Photo taken of the well location, facing west. See comments under Photo 1.

Inspection Photos
Location Name: UPRC #9-14K
Location ID: 327749



Photo 5. Photo taken of ground cover at the well location. Photo illustrates evidence of drill row seeding with weedy annual vegetation including kochia (*Bassia scoparia*).



Photo 6. Photo taken of the reference area to the location, east of the location, facing east. Photo illustrates perennial grass and weedy annual vegetation.