

Final Reclamation Inspection

February 13, 2026

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 327647

Inspection Document #: 718801401

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: HSR-ROZEMA #4-26A
Location ID: 327647



Photo 1. Photo taken of the well location, facing north. Photo illustrates that final reclamation activities appear to have taken place, but vegetation establishment does not meet Rule 1004 standards. Gravel and weedy annual vegetation including russian thistle (*Salsola tragus*) were observed at the location.



Photo 2. Photo taken of the well location, facing east. See comments under Photo 1.

Inspection Photos
Location Name: HSR-ROZEMA #4-26A
Location ID: 327647



Photo 3. Photo taken of the well location, facing south. See comments under Photo 1.



Photo 4. Photo taken of the well location, facing west. See comments under Photo 1.

Inspection Photos
Location Name: HSR-ROZEMA #4-26A
Location ID: 327647



Photo 5. Photo taken of ground cover at the well location. Photo illustrates bare ground, gravel, and weedy annual vegetation including russian thistle (*Salsola tragus*).



Photo 6. Photo taken of the access road to the location, facing south, away from the location. Photo illustrates that final reclamation activities appear to have taken place, but vegetation has not established to Rule 1004 standards.

Inspection Photos
Location Name: HSR-ROZEMA #4-26A
Location ID: 327647



Photo 7. Photo taken of the tank battery location, facing south. Photo illustrates that final reclamation activities have taken place, with evidence of drill row seeding, but vegetation has not established to Rule 1004 standards.



Photo 8. Photo taken of the tank battery location, facing north. See comments under Photo 7.

Inspection Photos
Location Name: HSR-ROZEMA #4-26A
Location ID: 327647



Photo 9. Photo taken of the tank battery location, facing west. See comments under Photo 7.



Photo 10. Photo taken of the access road to the tank battery location, facing north. Photo illustrates that final reclamation activities appear to have taken place, but vegetation has not established to Rule 1004 standards and bare ground remains across the access road.



Inspection Photos
Location Name: HSR-ROZEMA #4-26A
Location ID: 327647



Photo 11. Photo taken of the reference area to the location, north of the well location, facing north. Photo illustrates sand sagebrush and weedy annual vegetation.