

Final Reclamation Inspection

February 13, 2026

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 327415

Inspection Document #: 718801406

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: HSR-FOGELMAN #6-26A
Location ID: 327415



Photo 1. Photo taken of the well location, facing north. Photo illustrates that final reclamation activities appear to have taken place and vegetation is establishing at the location.



Photo 2. Photo taken of the well location, facing east. See comments under Photo 1.

Inspection Photos
Location Name: HSR-FOGELMAN #6-26A
Location ID: 327415



Photo 3. Photo taken of the well location, facing south. See comments under Photo 1.



Photo 4. Photo taken of the well location, facing west. See comments under Photo 1.

Inspection Photos
Location Name: HSR-FOGELMAN #6-26A
Location ID: 327415



Photo 5. Photo taken of ground cover at the well location. Photo illustrates bare ground, perennial grass, and weedy annual vegetation including russian thistle (*Salsola tragus*) and kochia (*Bassia scoparia*).



Photo 6. Photo taken of the access road to the location, facing southeast, towards the location. Photo illustrates that final reclamation activities appear to have taken place, but vegetation has not established to Rule 1004 standards.

Inspection Photos
Location Name: HSR-FOGELMAN #6-26A
Location ID: 327415



Photo 7. Photo taken of the access road to the location, facing west, away from the location. See comments under Photo 6.



Photo 8. Photo taken of the reference area to the location, east of the location, facing east. Photo illustrates perennial grass and weedy annual vegetation.

