

# Final Reclamation Inspection

February 13, 2026

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 327214

Inspection Document #: 718801411

Weld County, CO

Katelyn Mitchem  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: HSR-STUBBEN #11-26A  
Location ID: 327214



**Photo 1.** Photo taken of the well location, facing north. Photo illustrates that final reclamation activities appear to have taken place, but vegetation establishment does not meet Rule 1004 standards.



**Photo 2.** Photo taken of the well location, facing east. See comments under Photo 1.

Inspection Photos  
Location Name: HSR-STUBBEN #11-26A  
Location ID: 327214



**Photo 3.** Photo taken of the well location, facing south. See comments under Photo 1.



**Photo 4.** Photo taken of the well location, facing west. See comments under Photo 1.



Inspection Photos  
Location Name: HSR-STUBBEN #11-26A  
Location ID: 327214



**Photo 5.** Photo taken of ground cover at the well location. Photo illustrates bare ground, mulch, and perennial grass.



**Photo 6.** Photo taken of the reference area to the location, southwest of the location, facing south. Photo illustrates sand sagebrush and weedy annual vegetation.

