

# Final Reclamation Inspection

February 13, 2026

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 336227

Inspection Document #: 718801415

Weld County, CO

Katelyn Mitchem  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Location Name: HSR-BEIERLE-63N66W/26SESW

Location ID: 336227



**Photo 1.** Photo taken of the multi-well location, facing north. Photo illustrates that final reclamation activities appear to have taken place, but vegetation establishment does not meet Rule 1004 standards.



**Photo 2.** Photo taken of the multi-well location, facing east. See comments under Photo 1.



Inspection Photos

Location Name: HSR-BEIERLE-63N66W/26SESW

Location ID: 336227



**Photo 3.** Photo taken of the multi-well location, facing south.  
See comments under Photo 1.



**Photo 4.** Photo taken of the multi-well location, facing west.  
See comments under Photo 1.



## Inspection Photos

Location Name: HSR-BEIERLE-63N66W/26SESW

Location ID: 336227



**Photo 5.** Photo taken of ground cover at the well location. Photo illustrates bare ground, perennial grass, and weedy annual vegetation.



**Photo 6.** Photo taken of the reference area to the location, west of the location, facing northeast. Photo illustrates sand sagebrush, perennial grass and weedy annual vegetation.

