

# Inspection Photos

API: 071-08267

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 3/11/2026

County: LAS ANIMAS



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing southeast along the access road. Additional BMP's appear to have recently been installed.



## Inspection Photos



**Photo 2.** Facing southeast along the access road.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API:071-08267 | Date: 3/11/2026

## Inspection Photos



**Photo 3.** Facing south toward the location.



## Inspection Photos



**Photo 4.** The vegetation around the equipment has had recent herbicide treatment.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API:071-08267 | Date: 3/11/2026