

Inspection Photos

API: 071-09246

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 3/11/2026

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southwest along the access road. The access road is stabilized and maintained in good condition.



Inspection Photos



Photo 2. Facing southwest along the access road. The access road is stabilized and maintained in good condition.



Inspection Photos



Photo 3. Facing south along the access road. The buried electric utilities remain along the road per approved variance.



Inspection Photos



Photo 4. Facing southeast along the road toward the location..



Inspection Photos



Photo 5. The buried electric utilities remain at the location per approved variance.



Inspection Photos



Photo 6. Facing east along the fill slope of the location which is stabilized with perennial desirable vegetation.



Inspection Photos



Photo 7. Facing southeast at the east side of the location. The vegetation has established to reference area levels.



Inspection Photos



Photo 8. Facing west at the location. The vegetation has established to reference area levels.



Inspection Photos



Photo 9. Facing toward the cut slope which is stabilized with perennial desirable vegetation.

