

Interim Reclamation and Stormwater Inspection

February 23, 2026

Operator: KP KAUFFMAN COMPANY INC - 46290

Location ID: 318979

Well Name: DORIS #12-34

Inspection Document #: 718601359

Weld County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: DORIS #12-34
Location ID: 318979



Photo 1. Photo taken looking east down the access road. Access road has been repaired.



Photo 2. Looking east across well site. Dead undesirable weedy plant species are present on location.



Inspection Photos
Location Name: DORIS #12-34
Location ID: 318979



Photo 3. Trash and debris is present inside the motor shed.



Photo 4. Stained soil present around engine. Close engine shed door to prevent unauthorized access. Flywheel does not have cover installed.



Inspection Photos
Location Name: DORIS #12-34
Location ID: 318979



Photo 5. Broken belts left in place around pulley.



Photo 6. Photo taken at the tank battery looking north at the separator. Undesirable weeds such as kochia are unmanaged on the location.



Inspection Photos
Location Name: DORIS #12-34
Location ID: 318979



Photo 7. Looking northwest across tank battery. Weedy undesirable plant species were present and unmanaged throughout location (Kochia, Russian thistle).



Photo 8. Uncapped pipes without wildlife exclusion devices at tank battery.



Inspection Photos
Location Name: DORIS #12-34
Location ID: 318979



Photo 9. Looking south across tank battery. Undesirable weeds are overgrown on location.

