

Interim Reclamation and Stormwater Inspection

February 23, 2026

Operator: KP KAUFFMAN COMPANY INC - 46290

Location ID: 464350

Location Name: Lone Eagle/13-34

Inspection Document #: 718601397

Weld County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Lone Eagle/13-34
Location ID: 464350



Photo 1. Looking south across the tank battery. All equipment remains on the location. Undesirable weeds are present throughout the location.



Photo 2. Looking east across the tank battery area. Undesirable weeds such as Kochia and Russian Thistle are present inside of secondary containment.



Inspection Photos
Location Name: Lone Eagle/13-34
Location ID: 464350



Photo 3. Looking northwest at the east side of the tank battery. Undesirable weeds inside of secondary containment. Unused equipment remains on site. The eastern tank has an open inspection hatch.



Photo 4. Looking south at the separator sheds on the southern side of location. Excavation and soil pile appear unchanged since last reclamation inspection (04/15/2025).

Inspection Photos
Location Name: Lone Eagle/13-34
Location ID: 464350



Photo 5. Soil pile remains on location. Stormwater BMPs around soil pile have degraded.



Photo 6. Looking east across the separator sheds. Weeds are present throughout the location.

