

Final Reclamation and Stormwater Inspection

February 23, 2025

Operator: KP KAUFFMAN COMPANY INC - 46290

Location ID: 319319

Well Name: BBR ABBOTT FARMS #22-34

Inspection Document #: 718601399

Weld County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: BBR ABBOTT FARMS #22-34
Location ID: 319319



Photo 1. Looking east down access road towards the well location from well API #123-10420. Access road appears to have been planted.



Photo 2. Looking northeast across the well location. Ste area surrounding the well has been planted.

Inspection Photos
Location Name: BBR ABBOTT FARMS #22-34
Location ID: 319319



Photo 3. Looking northeast across well location. Soil piles remain on location. Excavation remains on location. Fencing around the excavation is down. The excavation is now filled with trash/debris.



Photo 4. Looking north across the open excavation and wellhead. Trash and debris is present in the open excavation.

