

Interim Reclamation and Stormwater Inspection

February 23, 2026

Operator: KP KAUFFMAN COMPANY INC - 46290

Location ID: 427114

Well Name: Bosky PC/Z22-14 Tank

Inspection Document #: 718601401

Weld County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: Bosky PC/Z22-14 Tank

Location ID: 427114



Photo 1. Photo taken looking north across tank battery. Undesirable weedy annual plant species are present throughout location. (Kochia, Russian thistle).



Photo 2. Looking west across tank battery. Weeds present inside secondary containment.



Inspection Photos

Location Name: Bosky PC/Z22-14 Tank

Location ID: 427114



Photo 3. Separator on location.



Photo 4. Looking northeast near the separator and produced water tank. Produced water tank does not have secondary containment.



Inspection Photos
Location Name: Bosky PC/Z22-14 Tank
Location ID: 427114



Photo 5. Produced water tank with no secondary containment.