

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA 23-26 Tank Pad

Location ID: 452297



Photo # 9000 From entrance to location




Photo # 9001 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA 23-26 Tank Pad

Location ID: 452297




Photo # 9002 Location



Photo # 9003 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA 23-26 Tank Pad

Location ID: 452297



Photo # 9004 Location




Photo # 9005 Battery sign lacks the public road used to access the Tank battery site & location, including the quarter/quarter section, of the Tank battery

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA 23-26 Tank Pad

Location ID: 452297




Photo # 9006 Battery sign lacks the public road used to access the Tank battery site & location, including the quarter/quarter section, of the Tank battery