

Inspection Photos

Operator: **LARAMIE ENERGY LLC - 10433**

Location Name: **MY WAY RANCH 18-5 PAD**

Location ID: **334552**

Inspection Date: **3/13/2026** Inspection Doc#: **693809191**



Location entrance with sign



Wellhead with fence and sign

Inspection Photos

Operator: **LARAMIE ENERGY LLC - 10433**

Location Name: **MY WAY RANCH 18-5 PAD**

Location ID: **334552**

Inspection Date: **3/13/2026** Inspection Doc#: **693809191**



Separators and Meter housing



Tank Battery

Inspection Photos

Operator: LARAMIE ENERGY LLC - 10433

Location Name: MY WAY RANCH 18-5 PAD


Location ID: 334552

Inspection Date: 3/13/2026 Inspection Doc#: 693809191



3/13/26, 11:55 AM
 39° 11' 30" N, 107° 55' 50" W
 316° NW
 Mesa County
 Energy & Carbon Management Commission

Telemetry



CALIBRATION					GAS ANALYSIS				
PLATE SIZE	DATE	CAL	INITIALS	DATE	SPECIFIC GRAVITY	BTU	H2S PPM	INITIALS	
IN	OUT								
0.750	0.750	1/5/23	YCS KM	1/28/22	0.746	1130.17	4	RD	
0.750	0.750	1/6/23	YCS KM	1/5/23	0.531	1076.99	4	TH	
0.750	0.750	1/29/24	YCS KM	1/29/24	0.656	1104.15	4	TH	
1.000	0.750	4/25/24	oil chung TH	-	-	-	-	-	
1.000	1.000	1/15/25	YCS KM	1/28/25	0.701	1095.86	5	TH	
1.000	1.000	1/14/26	YCS KM	1/7/26	0.675	1123.72	4	TH	

3/13/26, 11:55 AM
 39° 11' 30" N, 107° 55' 50" W
 219° SW
 Mesa County
 Energy & Carbon Management Commission

Calibration card

Inspection Photos

Operator: **LARAMIE ENERGY LLC - 10433**

Location Name: **MY WAY RANCH 18-5 PAD**

Location ID: **334552**

Inspection Date: **3/13/2026** Inspection Doc#: **693809191**



3/13/26, 11:54 AM
39° 11' 29" N, 107° 55' 47" W
281° W
Mesa County
Energy & Carbon Management Commission

Location overview looking W