

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
404168560

Date Received:  
03/16/2026

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 17180  
Name of Operator: CITATION OIL & GAS CORP  
Address: 14077 CUTTEN RD  
City: HOUSTON State: TX Zip: 77069

Contact Name and Telephone:  
Name:  
Phone: ( ) Fax: ( )  
Email:

Additional Operator Contact:

Contact Name	Phone	Email
<u>Redweik, Bob</u>	<u>(281) 891-1550</u>	<u>bredweik@cogc.com</u>
<u>Costa, Ryan</u>		<u>ryan.costa@state.co.us</u>
<u>Joel Mason</u>		<u>joel.mason@absarokasolutions.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 715200427  
Inspection Date: 06/26/2024 FIR Submit Date: 06/30/2024 FIR Status:

Inspected Operator Information:

Company Name: CITATION OIL & GAS CORP Company Number: 17180  
Address: 14077 CUTTEN RD  
City: HOUSTON State: TX Zip: 77069

LOCATION - Location ID: 321628

Location Name: MOUNT PEARL UNIT-613S48W Number: 25NWSW County: CHEYENNE  
Qtrqtr: NWS Sec: 25 Twp: 13S Range: 48W Meridian: 6  
Latitude: 38.886224 Longitude: -102.738757

FACILITY - API Number: 05-017-00 Facility ID: 207573

Facility Name: MOUNT PEARL UNIT Number: 13-25  
Qtrqtr: NWS Sec: 25 Twp: 13S Range: 48W Meridian: 6  
Latitude: 38.886224 Longitude: -102.738757

CORRECTIVE ACTIONS:

1 CA# 196306

Corrective Action: Continue with final reclamation process Date:

Response: CA COMPLETED Date of Completion: 04/22/2025

On April 22, 2025, a site inspection was performed at the location. A row crop (wheat) was observed to be

Operator Comment: planted at the location. Numerous bare spots were observed all over the field. (see attachment A). Four (4) agronomy confirmation samples were obtained from the corners of the former pad location at depths of 0-6", 6-12", and 12-24" . A single background sample was obtained from 350 feet Northeast of the location. The samples were sent to the CSU soil laboratory. Analytical results showed the site has low nutrient availability (see attachment B for analytical results). Finished compost will be applied to the location and tilled in prior to the next crop rotation in coordination with the property owner in compliance with 1004 series rules.

ECMC Decision: \_\_\_\_\_

ECMC Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Bob Redweik

Signed: \_\_\_\_\_

Title: VP – EHS and Regulatory

Date: 3/16/2026 7:23:37 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<b>Document Number</b>	<b>Description</b>
404465793	Attachment B- Analytical
404465837	Attachment A- Site Photographs

Total Attach: 2 Files