

TABLE 1
 915-1 Organic Analytes - Soil Samples
 T035 Grid Sampling 6/30

lab sdg	lab sdg
L1874747	L1874747

Notes:
 Bold and Pink or Yellow highlighted soil analytical values indicate an exceedance of the referenced soil screening level (SSL).
 Pink cells indicate an exceedance of the Residential SSL also exceeds the Protection of Groundwater SSL except for benzo(a)pyrene.
 NE indicates that SSLs have not been established for this parameter.
 Pace National-Laboratory non-detections reported by the laboratory prior to 5/9/2025 are reported as less than ("<") the laboratory method detection limit. Pace National-Laboratory non-detections reported by the laboratory beginning on 5/9/2025 and Enthalpy - Laboratory non-detections are reported as less than ("<") the limit of quantitation.
 Multiple columns are presented for individual analytes when laboratories perform and/or report multiple analyses (such as original analyses, reanalyses, and dilution analyses). All available data are shown for events with more than one reportable result, with each column representing a distinct analysis.
 Italic values indicate that the laboratory-reported method detection limit and/or quantitation limit associated with the non-detected result is higher than the threshold concentration.
 Sampling and analysis is being performed in accordance with the approved ESAP.
 NA represents not analyzed.
 ND represents not-detected for calculated results that do not have a laboratory reporting limit. All results associated with the calculation of the analyte were not-detected.
 Soil TPH = (total volatile and extractable hydrocarbons).
 (DUP) indicates Field Duplicate Samples.
 ECMC = Colorado Energy and Carbon Management Commission

No parameters were detected at concentrations exceeding ECMC Table 915-1 Residential SSLs.

Data Qualifiers

U: The analyte was analyzed for, but was not detected above the level of the adjusted detection limit or quantitation limit, as appropriate, or was observed in a blank at a similar level.
 R: The data are unusable. The sample results are rejected due to serious deficiencies in meeting QC criteria. The analyte may or may not be present in the sample.
 J: The result is an estimated quantity. The associated numerical value is the approximate concentration of the analyte in the sample.
 J+: The result is an estimated quantity, but the result may be biased high.
 J-: The result is an estimated quantity, but the result may be biased low.
 UJ: The analyte was analyzed for but was not detected. The reported quantitation limit is approximate and may be inaccurate or imprecise.

Units:

mg/kg = Milligrams per kilogram

TABLE 1
915-1 Organic Analytes - Soil Samples
T035 Grid Sampling 6/30

Sample ID	Location	Sample Date	Depth	Sample Purpose	SW8270-SIM								
					1-METHYLNAPHTHALENE	2-METHYLNAPHTHALENE	ACENAPHTHENE	ANTHRACENE	BENZO(A)ANTHRACENE	BENZO(A)PYRENE	BENZO(B)FLUORANTHENE	FLUORENE	NAPHTHALENE
					mg/kg	mg/kg	mg/kg	mg/kg	mg/kg	mg/kg	mg/kg	mg/kg	mg/kg
ECMC Table 915-1 Limits (Soil TPH)					NE	NE	NE	NE	NE	NE	NE	NE	NE
ECMC Table 915-1 Limits (Residential SSL)					18	24	360	1800	1.1	0.11	1.1	240	2
ECMC Table 915-1 Limits (Protection of Groundwater SSL)					0.006	0.019	0.55	5.8	0.011	0.24	0.3	0.54	0.0038
GACO0630T035C001	T035C001 (DUP)	06/30/2025	0-0.5 feet	Assessment/Delineation	<0.0033 U	<0.0132 U	<0.0363 U	<0.0363 U	<0.00661 U	<0.0363 U	<0.0363 U	<0.0363 U	<0.0033 U
GACO0630T035S001	T035S001	06/30/2025	0-0.5 feet	Assessment/Delineation	<0.00331 U	<0.0132 U	<0.0364 U	<0.0364 U	<0.00661 U	<0.0364 U	<0.0364 U	<0.0364 U	<0.00331 U
GACO0630T035S002	T035S002	06/30/2025	0-0.5 feet	Assessment/Delineation	<0.00353 U	<0.0141 U	<0.0388 U	<0.0388 U	<0.00705 U	<0.0388 U	<0.0388 U	<0.0388 U	<0.00353 U
GACO0630T035S003	T035S003	06/30/2025	0-0.5 feet	Assessment/Delineation	<0.00319 U	<0.0127 U	<0.0351 U	<0.0351 U	<0.00637 U	<0.0351 U	<0.0351 U	<0.0351 U	<0.00319 U
GACO0630T035S004	T035S004	06/30/2025	0-0.5 feet	Assessment/Delineation	<0.00377 U	<0.0151 U	<0.0415 U	<0.0415 U	<0.00755 U	<0.0415 U	<0.0415 U	<0.0415 U	<0.00377 U
GACO0630T035S005	T035S005	06/30/2025	0-0.5 feet	Assessment/Delineation	<0.00334 U	<0.0134 U	<0.0367 U	<0.0367 U	<0.00668 U	<0.0367 U	<0.0367 U	<0.0367 U	<0.00334 U
GACO0630T035S006	T035S006	06/30/2025	0-0.5 feet	Assessment/Delineation	<0.00321 U	<0.0129 U	<0.0353 U	<0.0353 U	<0.00643 U	<0.0353 U	<0.0353 U	<0.0353 U	<0.00321 U
GACO0630T035S007	T035S007	06/30/2025	0-0.5 feet	Assessment/Delineation	<0.00316 U	<0.0126 U	<0.0347 U	<0.0347 U	<0.00632 U	<0.0347 U	<0.0347 U	<0.0347 U	<0.00316 U
GACO0630T035S008	T035S008	06/30/2025	0-0.5 feet	Assessment/Delineation	<0.00317 U	<0.0127 U	<0.0349 U	<0.0349 U	<0.00635 U	<0.0349 U	<0.0349 U	<0.0349 U	<0.00317 U

Notes:
 Bold and Pink or Yellow highlighted soil analytical values indicate an exceedance of the referenced soil screening level (SSL).
 Pink cells indicate an exceedance of the Residential SSL also exceeds the Protection of Groundwater SSL except for benzo(a)pyrene.
 NE indicates that SSLs have not been established for this parameter.
 Pace National-Laboratory non-detections reported by the laboratory prior to 5/9/2025 are reported as less than ("<") the laboratory method detection limit. Pace National-Laboratory non-detections reported by the laboratory beginning on 5/9/2025 and Enthalpy - Laboratory non-detections are reported as less than ("<") the limit of quantitation.
 Multiple columns are presented for individual analytes when laboratories perform and/or report multiple analyses (such as original analyses, reanalyses, and dilution analyses). All available data are shown for events with more than one reportable result, with each column representing a distinct analysis.
 Italic values indicate that the laboratory-reported method detection limit and/or quantitation limit associated with the non-detected result is higher than the threshold concentration.
 Sampling and analysis is being performed in accordance with the approved ESAP.
 NA represents not analyzed.
 ND represents not-detects for calculated results that do not have a laboratory reporting limit. All results associated with the calculation of the analyte were not-detected.
 Soil TPH = (total volatile and extractable hydrocarbons).
 (DUP) indicates Field Duplicate Samples.
 ECMC = Colorado Energy and Carbon Management Commission

No parameters were detected at concentrations exceeding ECMC Table 915-1 Residential SSLs.

Data Qualifiers

U: The analyte was analyzed for, but was not detected above the level of the adjusted detection limit or quantitation limit, as appropriate, or was observed in a blank at a similar level.
 R: The data are unusable. The sample results are rejected due to serious deficiencies in meeting QC criteria. The analyte may or may not be present in the sample.
 J: The result is an estimated quantity. The associated numerical value is the approximate concentration of the analyte in the sample.
 J+: The result is an estimated quantity, but the result may be biased high.
 J-: The result is an estimated quantity, but the result may be biased low.
 UJ: The analyte was analyzed for but was not detected. The reported quantitation limit is approximate and may be inaccurate or imprecise.

Units:

mg/kg = Milligrams per kilogram

TABLE 1
915-1 Organic Analytes - Soil Samples
T035 Grid Sampling 6/30

Sample ID	Location	Sample Date	Depth	Sample Purpose	SW8270-SIM	SW8260						SW8015	SW8015M
					PYRENE	1,2,4-TRIMETHYLBENZENE	1,3,5-TRIMETHYLBENZENE	BENZENE	ETHYLBENZENE	TOLUENE	TOTAL XYLENES	TVPH - GASOLINE RANGE ORGANICS	C10-C28 DIESEL RANGE ORGANICS
					mg/kg	mg/kg	mg/kg	mg/kg	mg/kg	mg/kg	mg/kg	mg/kg	mg/kg
ECMC Table 915-1 Limits (Soil TPH)					NE	NE	NE	NE	NE	NE	NE	NE	NE
ECMC Table 915-1 Limits (Residential SSL)					180	30	27	1.2	5.8	490	58	NE	NE
ECMC Table 915-1 Limits (Protection of Groundwater SSL)					1.3	0.0081	0.0087	0.0026	0.78	0.69	9.9	NE	NE
GACO0630T035C001	T035C001 (DUP)	06/30/2025	0-0.5 feet	Assessment/Delineation	<0.0363 U	<0.0241 U	<0.0241 U	0.00806	<0.0481 U	0.0544	<0.481 U	<3.01 U	<4.41 U
GACO0630T035S001	T035S001	06/30/2025	0-0.5 feet	Assessment/Delineation	<0.0364 U	<0.00602 U	<0.00602 U	<0.0012 U	<0.012 U	<0.012 U	<0.12 U	<3.01 U	<4.41 U
GACO0630T035S002	T035S002	06/30/2025	0-0.5 feet	Assessment/Delineation	<0.0388 U	<0.00676 U	<0.00676 U	<0.00135 U	<0.0135 U	<0.0135 U	<0.135 U	<3.38 U	<23.5 U
GACO0630T035S003	T035S003	06/30/2025	0-0.5 feet	Assessment/Delineation	<0.0351 U	<0.00562 U	<0.00562 U	<0.00112 U	<0.0112 U	<0.0112 U	<0.112 U	<2.81 U	5.01
GACO0630T035S004	T035S004	06/30/2025	0-0.5 feet	Assessment/Delineation	<0.0415 U	<0.00758 U	<0.00758 U	<0.00152 U	<0.0152 U	<0.0152 U	<0.152 U	<3.79 U	<5.03 U
GACO0630T035S005	T035S005	06/30/2025	0-0.5 feet	Assessment/Delineation	<0.0367 U	<0.00613 U	<0.00613 U	<0.00123 U	<0.0123 U	<0.0123 U	<0.123 U	<3.06 U	<4.45 U
GACO0630T035S006	T035S006	06/30/2025	0-0.5 feet	Assessment/Delineation	<0.0353 U	<0.00571 U	<0.00571 U	<0.00114 U	<0.0114 U	<0.0114 U	<0.114 U	<2.86 U	4.79
GACO0630T035S007	T035S007	06/30/2025	0-0.5 feet	Assessment/Delineation	<0.0347 U	<0.00553 U	<0.00553 U	<0.00111 U	<0.0111 U	<0.0111 U	<0.111 U	<2.76 U	6.15
GACO0630T035S008	T035S008	06/30/2025	0-0.5 feet	Assessment/Delineation	<0.0349 U	<0.00558 U	<0.00558 U	<0.00112 U	<0.0112 U	<0.0112 U	<0.112 U	<2.79 U	5.15

Notes:
 Bold and Pink or Yellow highlighted soil analytical values indicate an exceedance of the referenced soil screening level (SSL).
 Pink cells indicate an exceedance of the Residential SSL also exceeds the Protection of Groundwater SSL except for benzo(a)pyrene.
 NE indicates that SSLs have not been established for this parameter.
 Pace National-Laboratory non-detections reported by the laboratory prior to 5/9/2025 are reported as less than ("<") the laboratory method detection limit. Pace National-Laboratory non-detections reported by the laboratory beginning on 5/9/2025 and Enthalpy - Laboratory non-detections are reported as less than ("<") the limit of quantitation.
 Multiple columns are presented for individual analytes when laboratories perform and/or report multiple analyses (such as original analyses, reanalyses, and dilution analyses). All available data are shown for events with more than one reportable result, with each column representing a distinct analysis.
 Italic values indicate that the laboratory-reported method detection limit and/or quantitation limit associated with the non-detected result is higher than the threshold concentration.
 Sampling and analysis is being performed in accordance with the approved ESAP.
 NA represents not analyzed.
 ND represents not-detects for calculated results that do not have a laboratory reporting limit. All results associated with the calculation of the analyte were not-detected.
 Soil TPH = (total volatile and extractable hydrocarbons).
 (DUP) indicates Field Duplicate Samples.
 ECMC = Colorado Energy and Carbon Management Commission

No parameters were detected at concentrations exceeding ECMC Table 915-1 Residential SSLs.

Data Qualifiers

U: The analyte was analyzed for, but was not detected above the level of the adjusted detection limit or quantitation limit, as appropriate, or was observed in a blank at a similar level.
 R: The data are unusable. The sample results are rejected due to serious deficiencies in meeting QC criteria. The analyte may or may not be present in the sample.
 J: The result is an estimated quantity. The associated numerical value is the approximate concentration of the analyte in the sample.
 J+: The result is an estimated quantity, but the result may be biased high.
 J-: The result is an estimated quantity, but the result may be biased low.
 UJ: The analyte was analyzed for but was not detected. The reported quantitation limit is approximate and may be inaccurate or imprecise.

Units:

mg/kg = Milligrams per kilogram

TABLE 1
915-1 Organic Analytes - Soil Samples
T035 Grid Sampling 6/30

Sample ID	Location	Sample Date	Depth	Sample Purpose	SW8015M	SW8015/M
					C28-C36 MOTOR OIL RANGE ORGANICS	TPH
					mg/kg	mg/kg
ECMC Table 915-1 Limits (Soil TPH)					NE	500
ECMC Table 915-1 Limits (Residential SSL)					NE	NE
ECMC Table 915-1 Limits (Protection of Groundwater SSL)					NE	NE
GACO0630T035C001	T035C001 (DUP)	06/30/2025	0-0.5 feet	Assessment/Delineation	25	25
GACO0630T035S001	T035S001	06/30/2025	0-0.5 feet	Assessment/Delineation	32.2	32.2
GACO0630T035S002	T035S002	06/30/2025	0-0.5 feet	Assessment/Delineation	102	102
GACO0630T035S003	T035S003	06/30/2025	0-0.5 feet	Assessment/Delineation	40.9	45.91
GACO0630T035S004	T035S004	06/30/2025	0-0.5 feet	Assessment/Delineation	22.3	22.3
GACO0630T035S005	T035S005	06/30/2025	0-0.5 feet	Assessment/Delineation	28.3	28.3
GACO0630T035S006	T035S006	06/30/2025	0-0.5 feet	Assessment/Delineation	45.8	50.59
GACO0630T035S007	T035S007	06/30/2025	0-0.5 feet	Assessment/Delineation	62	68.15
GACO0630T035S008	T035S008	06/30/2025	0-0.5 feet	Assessment/Delineation	49	54.15

Notes:
 Bold and Pink or Yellow highlighted soil analytical values indicate an exceedance of the referenced soil screening level (SSL).
 Pink cells indicate an exceedance of the Residential SSL also exceeds the Protection of Groundwater SSL except for benzo(a)pyrene.
 NE indicates that SSLs have not been established for this parameter.
 Pace National-Laboratory non-detections reported by the laboratory prior to 5/9/2025 are reported as less than (" $<$ ") the laboratory method detection limit. Pace National-Laboratory non-detections reported by the laboratory beginning on 5/9/2025 and Enthalpy - Laboratory non-detections are reported as less than (" $<$ ") the limit of quantitation.
 Multiple columns are presented for individual analytes when laboratories perform and/or report multiple analyses (such as original analyses, reanalyses, and dilution analyses). All available data are shown for events with more than one reportable result, with each column representing a distinct analysis.
 Italic values indicate that the laboratory-reported method detection limit and/or quantitation limit associated with the non-detected result is higher than the threshold concentration.
 Sampling and analysis is being performed in accordance with the approved ESAP.
 NA represents not analyzed.
 ND represents not-detects for calculated results that do not have a laboratory reporting limit. All results associated with the calculation of the analyte were not-detected.
 Soil TPH = (total volatile and extractable hydrocarbons).
 (DUP) indicates Field Duplicate Samples.
 ECMC = Colorado Energy and Carbon Management Commission

No parameters were detected at concentrations exceeding ECMC Table 915-1 Residential SSLs.

Data Qualifiers

U: The analyte was analyzed for, but was not detected above the level of the adjusted detection limit or quantitation limit, as appropriate, or was observed in a blank at a similar level.
 R: The data are unusable. The sample results are rejected due to serious deficiencies in meeting QC criteria. The analyte may or may not be present in the sample.
 J: The result is an estimated quantity. The associated numerical value is the approximate concentration of the analyte in the sample.
 J+: The result is an estimated quantity, but the result may be biased high.
 J-: The result is an estimated quantity, but the result may be biased low.
 UJ: The analyte was analyzed for but was not detected. The reported quantitation limit is approximate and may be inaccurate or imprecise.

Units:

mg/kg = Milligrams per kilogram