

# Inspection Photos

API: 071-06219

Operator: OGRIS OPERATING LLC

Inspection Date: 3/16/2026

County: LAS ANIMAS



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing northwest at the location. There is an active road that goes thru the center of the location..



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API:071-06219 | Date: 3/16/2026

## Inspection Photos



**Photo 2.** Facing west at the location. The location has not been contoured back to original contours shown at red arrows.



## Inspection Photos



**Photo 3.** Facing southwest at the location. The location has not been contoured back to original contours shown at red arrows. .



## Inspection Photos



**Photo 4.** Facing southeast along the fill slope.



## Inspection Photos



**Photo 5.** Facing north along the fill slope



## Inspection Photos



**Photo 6.** Standing on the access road facing north toward the fill slope shown at red arrow.

