

Final Reclamation Inspection

February 19, 2026

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 317547

Inspection Document #: 718801420

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: UPRR 22 PAN AM A #1
Location ID: 317547



Photo 1. Photo taken of the well location, facing north. Photo illustrates that final reclamation activities appear to have taken place at the well location, but vegetation establishment does not meet Rule 1004 standards as weedy annual vegetation including cheatgrass (*Bromus tectorum*), a List C Noxious Weed species was observed at the location. Fencing is in place surrounding the location.



Photo 2. Photo taken of the well location, facing east. See comments under Photo 1.

Inspection Photos
Location Name: UPRR 22 PAN AM A #1
Location ID: 317547



Photo 3. Photo taken of the well location, facing south. See comments under Photo 1.



Photo 4. Photo taken of the well location, facing west. See comments under Photo 1.

Inspection Photos

Location Name: UPRR 22 PAN AM A #1

Location ID: 317547



Photo 5. Photo taken of ground cover at the well location. Photo illustrates bare ground, perennial grass, and weedy annual vegetation including cheatgrass (*Bromus tectorum*), a List C Noxious Weed species.



Photo 6. Photo taken of the well location, facing southwest. Photo illustrates that a fence remains surrounding the location.



Inspection Photos
Location Name: UPRR 22 PAN AM A #1
Location ID: 317547



Photo 7. Photo taken of the reference area to the location, south of the location, facing northeast. Photo illustrates perennial grass and weedy annual vegetation.

