

Final Reclamation Inspection

February 19, 2026

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 305125

Inspection Document #: 718801424

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: FARLEY #19-23
Location ID: 305125



Photo 1. Photo taken of the well location, facing north. Photo illustrates that final reclamation activities appear to have taken place at the well location, but vegetation establishment does not meet Rule 1004 standards and weedy annual vegetation including cheatgrass (*Bromus tectorum*), a List C Noxious Weed species was observed at the location. Fencing is in place surrounding the location.



Photo 2. Photo taken of the well location, facing east. See comments under Photo 1.

Inspection Photos
Location Name: FARLEY #19-23
Location ID: 305125



Photo 3. Photo taken of the well location, facing south. See comments under Photo 1.



Photo 4. Photo taken of the well location, facing west. See comments under Photo 1.

Inspection Photos
Location Name: FARLEY #19-23
Location ID: 305125



Photo 5. Photo taken of ground cover at the well location. Photo illustrates bare ground, perennial grass, and weedy annual vegetation including cheatgrass (*Bromus tectorum*), a List C Noxious Weed species.



Photo 6. Photo taken of the access road to the well location, facing south, towards the location. Photo illustrates that final reclamation activities have taken place along the access road, but vegetation has not established to Rule 1004 standards.

Inspection Photos
Location Name: FARLEY #19-23
Location ID: 305125



Photo 7. Photo taken of the access road to the well location, facing southeast, towards the location. See comments under Photo 6.



Photo 8. Photo taken of the well location, facing west. Photo illustrates that the fence is in disrepair along this portion of the location.



Inspection Photos
Location Name: FARLEY #19-23
Location ID: 305125



Photo 9. Photo taken of the reference area to the location, southeast of the location, facing northeast. Photo illustrates perennial grass and weedy annual vegetation.

