

Final Reclamation Inspection

February 19, 2026

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 327115

Inspection Document #: 718801432

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: HSR-MORGAN #11-23
Location ID: 327115



Photo 1. Photo taken of the well location, facing north. Photo illustrates that final reclamation activities appear to have taken place, but vegetation establishment does not meet Rule 1004 standards and weedy annual vegetation including cheatgrass (*Bromus tectorum*), a List C Noxious Weed species, was observed at the location. An access road to a shut-in well runs through the location.



Photo 2. Photo taken of the well location, facing east. See comments under Photo 1.

Inspection Photos
Location Name: HSR-MORGAN #11-23
Location ID: 327115



Photo 3. Photo taken of the well location, facing south. See comments under Photo 1.



Photo 4. Photo taken of the well location, facing west. See comments under Photo 1.

Inspection Photos
Location Name: HSR-MORGAN #11-23
Location ID: 327115



Photo 5. Photo taken of ground cover at the well location. Photo illustrates bare ground, perennial grass, and weedy annual vegetation including cheatgrass (*Bromus tectorum*), a List C Noxious Weed species.



Photo 6. Photo taken of the reference area to the location, southeast of the location, facing north. Photo illustrates perennial grass and weedy annual vegetation.