

Inspection Photos

API: 071-06296

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 3/16/2026

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing northeast at the access road. The cattle guard has been cleaned out and is in good condition.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:071-06296 | Date: 3/16/2026

Inspection Photos



Photo 2. Facing southeast toward the wellsite.

