

Inspection Photos

03/11/2026

Operator: Koch Exploration Company #49100

Location ID: 316191

Inspection Doc: 719200942

Rio Blanco County, CO

Emily Gaasche
NW Reclamation Specialist
ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: Koch Exploration Company #49100

Location ID: 316191



Photo 1: Photos showing an overview of the location looking north and south, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: Koch Exploration Company #49100

Location ID: 316191



Photo 2: Photos showing an overview of the location looking east and west, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: Koch Exploration Company #49100

Location ID: 316191



Photo 3: Electrical equipment that does not appear to be in use is present on the southwestern corner of the location. Removal is required; comply with Rule 1004.a.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: Koch Exploration Company #49100

Location ID: 316191



Photo 4: Photos showing access roads leading to the location have established native vegetation. Dispersed gravel is present in some places.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: Koch Exploration Company #49100

Location ID: 316191



Photo 5: Photos showing that portions of the location appear to be poorly recontoured; however, mature vegetation has established and additional recontouring efforts are not required at this time.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: Koch Exploration Company #49100

Location ID: 316191



Photo 6: Photos showing examples of prickly Russian thistle and cheatgrass, an undesirable weedy annual and a noxious weed species, scattered throughout the location in secondary to tertiary amounts. Weed control is advised; a follow-up inspection will be conducted during future growing seasons to fully assess vegetation composition and cover.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: Koch Exploration Company #49100

Location ID: 316191



Photo 7: Photo showing a general overview of the location looking southwest.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources