

Audit Photos

Location Name: VISION ENERGY LLC, FEDERAL-68S97W/30SWSW

Location ID: 312470

Date: 3/16/2026



Location Overview – Photo #03094



Location/Weeds – Photo #03095

Audit Photos

Location Name: VISION ENERGY LLC, FEDERAL-68S97W/30SWSW

Location ID: 312470

Date: 3/16/2026



Location/Weeds – Photo #03100



Location/Weeds – Photo #03107

Audit Photos

Location Name: VISION ENERGY LLC, FEDERAL-68S97W/30SWSW

Location ID: 312470

Date: 3/16/2026



Location/Weeds – Photo #03101



Debris – Photo #03097

Audit Photos

Location Name: VISION ENERGY LLC, FEDERAL-68S97W/30SWSW

Location ID: 312470

Date: 3/16/2026



Mar 16, 2026 at 14:29:08
+39.325886, -108.266643
De Beque CO 81630
United States

Debris – Photo #03102



Mar 16, 2026 at 14:32:47
+39.325866, -108.266594
De Beque CO 81630
United States

Weeds – Photo #03111

Audit Photos

Location Name: VISION ENERGY LLC, FEDERAL-68S97W/30SWSW

Location ID: 312470

Date: 3/16/2026



Wildlife Entry – Photo #03104



Unsecured Gas Meter House – Photo #03109

Audit Photos

Location Name: VISION ENERGY LLC, FEDERAL-68S97W/30SWSW

Location ID: 312470

Date: 3/16/2026



**Inaccurate Operator Information on Wellhead Sign – Photo
#03096**