

Inspection Photos
Location Name: Beta 14-10 TR
Location ID: 308329



Photo 1 Location access rd.



Photo 2 Location.

Inspection Photos
Location Name: Beta 14-10 TR
Location ID: 308329



Photo 3 Location.

Photo 4 Gas Meters & Pig station.

Inspection Photos
Location Name: Beta 14-10 TR
Location ID: 308329



Photo 5 Well sign.

Photo 6 Well sign.

Inspection Photos
Location Name: Beta 14-10 TR
Location ID: 308329



Photo 7 Lined Pit.



Photo 8 Lined Pit.

Inspection Photos
Location Name: Beta 14-10 TR
Location ID: 308329



Photo 9 Wellhead Gas Skid engine.



Photo 10 Wellhead.

Inspection Photos
Location Name: Beta 14-10 TR
Location ID: 308329



Photo 11 Stained soil by skid engine gas valve.

Photo 12 Stained soil by skid engine gas valve.

Inspection Photos
Location Name: Beta 14-10 TR
Location ID: 308329



Photo 13 Electric panel & meter box.

Photo 14 Wellhead & Automation control panel.

Inspection Photos
Location Name: Beta 14-10 TR
Location ID: 308329



Photo 15 Wellhead.



Photo 16 Unlined/unused pit in process of closure.

Inspection Photos
Location Name: Beta 14-10 TR
Location ID: 308329



Photo 17 Unlined/unused pit in process of closure.

Photo 16 Unlined/unused pit in process of closure.