

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/17/2026

Submitted Date:

03/17/2026

Document Number:

719001617

FIELD INSPECTION FORM

Loc ID: 326557 Inspector Name: GARCIA, CHARLES On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10749
Name of Operator: SIMCOE LLC
Address: 1199 MAIN AVE SUITE 101
City: DURANGO State: CO Zip: 81301

Findings:

2 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		ehsinspections@machnr.com	
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
257165	WELL	PR	10/30/2000	CBM	067-08296	LUDWIG 2	PR

General Comment:

Inspection Report Summary
On 3/17/26 | Inspector Charles Garcia conducted an on-site follow up inspection.
Location: LUDWIG #2
Operator: Simcoe LLC
API#: 067-08296
County: LaPlata
DOC#719001388
FIR#404571093
ALL CAS RESOLVED

