

Inspection Photos
Location Name: PETTINGER-66N64W/2SWSE
Location #: 305860



Photo #1
Pettinger 34-2 (123-23591) Wellsite
Temporarily Abandoned | TA



Photo #2
Pettinger 34-2 Wellsite
Temporarily Abandoned | TA
macro view



Inspection Photos

Location Name: PETTINGER-66N64W/2SWSE

Location #: 305860



Photo #3

Pettinger 34-2 Wellsite

Temporarily Abandoned | TA

Wellsite(s) entrance



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: PETTINGER-66N64W/2SWSE

Location #: 305860



Photo #4

Pettinger 34-2 Battery site

Inactive | Shut-down

Equipment Documented; Loc ID: 305860

Formerly served:

Pettinger 33-2, 43-2, 44-2; Plugged & Abandoned | PA



Photo #5

Pettinger 34-2 Battery site

Inactive | Shut-down

Battery entrance



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources