

## Inspection Photos

Location Name: PETTINGER-66N64W/2NESE

Location #: 305861



### Photo #1

**Pettinger 43-2 (123-23592) Wellsite**

**Plugged & Abandoned | PA**

*Cut / Capped*

*~ 40 yds.*



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Location Name: PETTINGER-66N64W/2NESE

Location #: 305861



**Photo #2**

**Pettinger 34-2** Battery site

**Inactive | Shut-down**

**Equipment Documented; Loc ID: 305860**

*Formerly served:*

*Pettinger 33-2, 43-2, 44-2; Plugged & Abandoned | PA*



**Photo #3**

**Pettinger 34-2** Battery site

**Inactive | Shut-down**

**Battery entrance**



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources