

Inspection Photos

Location Name: PETTINGER-66N64W/2SWSE

Location #: 305860



Photo #1

Pettinger 34-2 Battery site

Inactive | Shut-down

Equipment Documented; Loc ID: 305860

Formerly served:

Pettinger 33-2, 43-2, 44-2; Plugged & Abandoned | PA



Photo #2

Pettinger 34-2 Battery site

Inactive | Shut-down

Battery entrance



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: PETTINGER-66N64W/2SWSE

Location #: 305860



Photo #3

Pettinger 34-2 Battery site

Inactive | Shut-down

Crude oil, produced H₂O tank(s): SE corner



Photo #4

Pettinger 34-2 Battery site

Inactive | Shut-down

ECD(s), Separator(s), Compressor(s)



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Location Name: PETTINGER-66N64W/2SWSE

Location #: 305860



Photo #5

Pettinger 34-2 Battery site

Inactive | Shut-down

Battery sign



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Location Name: PETTINGER-66N64W/2SWSE

Location #: 305860

Associated Well(s)	API	Status
<i>Wellsite^</i>		<i>LOC # 305860</i>
1. Pettinger 34-2	123-23591	TA

Photo #6

Pettinger 34-2 Battery site

Inactive | Shut-down

Associated Well(s): 1

Temporarily Abandoned | TA



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources